a divertised and to main the main to main the main to main the main to main to main to main the main								
BUSCHAUTION Image: State of the state	N . OF COPIES RECEIVED	-1			•	Form C-103		
Active in the second	DISTRIBUTION					Supersedes Old		
11.5.0.3 Indicator Type of Leave 12.6.0.2 State Of A Via Leave Soc 0.7.7.7.0 B-2516 13.6.10 SUNDRY HOTICES AND REPORTS ON WELLS. 14.6.10 Ministry Social And And Leave Social And	NEW MEXICO OIL CONSERVATION COMMISSION							
LAND GEVICE	FILE				-			
CPERATOR State of the cut the property notices AND REPORTS ON WELLS B-2616 Construct to the cut the property notices AND REPORTS ON WELLS Total total cut the property notices AND REPORTS ON WELLS Total total cut	U.S.G.S.	_					of Lease	
Image: Production Company File Anoco Production Company State D Amoco Production Company State D Anoco Production Company State D Plot Another A company State D Intervention Another A company State D Interent	LAND OFFICE					F 4	· · · · · · · · · · · · · · · · ·	
SUNCRY NOTICES AND REPORTS ON WELLS ************************************	OPERATOR						s Lease No.	
Construction of the second of the secon	SUM	DV HOTICE	SAND DEDODTS ON	W/ETIC			mmm	
**** X order. ***** State D ***** State D ****** State D ******* State D ********** State D ************************************	DO NOT USE THIS FORM FOR P UNI MAPPLICA	REPOSALS TO DR NTION FER FERMI	ILL OR TO DEEPEN OR PLUG D ILL OR TO DEEPEN OR PLUG D IT - " (FORM C-101) FOR SUC	ITELLED ACK TO A DIFFERENT RESERVOI H PROPOSALS.)	R			
Intervent E. Farror Leave Have Amage Production Company State D Attest if creat. 9. Will No. P.O. Drawer A, Levelland, Texas 79336 9. Will No. States if creat. 9. Will No. State D 10. Flat and Fool, or Kitson Lead 11. Execute Not. State D 12. County Its is creat. 13. Execute Not. State D 14. Could Make State. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: States is creat. Fue And Asadors State D State D State D		X OTHER.				7. Unit Agreement	Name	
A Have of Cleman 9. Woll Res P.O. Drawer A, Levelland, Texas 79336 10. Pield and Peol, or Willow Lecentor deal 10. Pield and Peol, or Willow Landline Kell 10. Pield and Peol, or Willow With Crites P 990 The Cast of Will 10. Pield and Peol, or Willow With Crites P 990 The Cast of Will 10. Field and Peol, or Willow With Crites P 990 The Cast of Will 10. Field and Peol, or Willow Landline Kell 10. Field and Peol, or Willow With Crites P 990 The Cast of Will 10. Field and Peol, or Willow Landline Kell 10. Field and Peol, or Willow With Crites P 990 The Cast of Will 10. Field and Peol, or Willow Landline Kell 10. Field and Peol, or Willow With You 24-5 Addet Stat Stat State State State State State 10. Field and Peol, or Willow With You 24-5 State State With You 10. Field and You 10. Field and You With You 10. Field and You 10. Field and You With You 10. F			<u></u>			6. Farm or Lease	Name	
P.0. Drawer A, Levelland, Texas 79336 5 ALLeratic of Weil 990 ref read for South contents and 330 ref read for South contents and 330 In terms P 990 ref read for South contents and 330 ref read for South contents and 330 In terms P 990 ref read for South contents and 330 ref read for South contents and content and contents and contents and cont		any		·				
2. Lecanize of Kell 990 ref read the	• • • •	and Texa	s 79336			9, Well No. 5		
ne east twe, settion 16 tweeter DF, RJ, GR, etc.J 12, Councy it Check Appropriate Box To Indicate Nature of Norice, Report or Other Data SUBSEQUENT REPORT OF: vit Check Appropriate Box To Indicate Nature of Norice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: vit PLUE AND ABADDAW tweeter term Appropriate Counce term vit Definition of Completed Operations (Cherry state all periment details, and give periment deta, including estimated date of stating any proposed vite in Service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test OK. Ran logs and perforated zone 3254'-78', 3283'-94' W/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' W/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing,						10. Field and Pool, or Wildcat		
ne east twe, settion 16 tweeter DF, RJ, GR, etc.J 12, Councy it Check Appropriate Box To Indicate Nature of Norice, Report or Other Data SUBSEQUENT REPORT OF: vit Check Appropriate Box To Indicate Nature of Norice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: vit PLUE AND ABADDAW tweeter term Appropriate Counce term vit Definition of Completed Operations (Cherry state all periment details, and give periment deta, including estimated date of stating any proposed vite in Service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test OK. Ran logs and perforated zone 3254'-78', 3283'-94' W/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' W/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing, packer, and 150' Valid perforated zone 3254'-78', 3283'-94' M/20PJSPF. Ran 2 3/8 tubing,	UNIT LETTER P	<u>990</u>	ET FROM THESOUTH_	LINE AND 330	FEET FROM	Langlie Ma	ttix Queen	
15. Elevation (Show whether DF, N1, CR, etc.) 12. County 2253.8 RDB Lea It address and the second and the second address addr						<u>IIIIIIII</u>	<u>IIIIIIIII</u>	
3253.8 RDB Lea NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Completion Completed State State OTHER INTENTION TO: SUBSEQUENT REPORT OF: OTHER INTENTION TO: Completed State State OTHER INTENTION TO: OTHER INTENTION <td col<="" td=""><td>THE <u>east</u> line, sect</td><td>пок 16</td><td> TOWNSHIP 24-S</td><td> RANGE</td><td> NMPM.</td><td></td><td></td></td>	<td>THE <u>east</u> line, sect</td> <td>пок 16</td> <td> TOWNSHIP 24-S</td> <td> RANGE</td> <td> NMPM.</td> <td></td> <td></td>	THE <u>east</u> line, sect	пок 16	TOWNSHIP 24-S	RANGE	NMPM.		
3253.8 RDB Lea NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Completion Completed State State OTHER INTENTION TO: SUBSEQUENT REPORT OF: OTHER INTENTION TO: Completed State State OTHER INTENTION TO: OTHER INTENTION <td col<="" td=""><td></td><td>11111</td><td>Elevation (Show whether</td><td>DF, KT, GR, etc.)</td><td> h</td><td>12. County</td><td>+++++++++++</td></td>	<td></td> <td>11111</td> <td>Elevation (Show whether</td> <td>DF, KT, GR, etc.)</td> <td> h</td> <td>12. County</td> <td>+++++++++++</td>		11111	Elevation (Show whether	DF, KT, GR, etc.)	h	12. County	+++++++++++
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: INTENTION TO: SUBSEQUENT REPORT OF: INTENTION TO: INTENTION TO: SUBSEQUENT REPORT OF: INTENTION TO: INTENTION TO: INTENTION TO: SUBSEQUENT REPORT OF: INTENTION TO: INTENTION INTENTION TO: INTENTION								
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUE AND AGANDON PLUE AND AGANDON ALTERINE CASING TEMPORAMELY ARANDON PLUE AND AGANDON HE HEDDAL WORK ALTERINE CASING TEMPORAMELY ARANDON EMARCE PLANS COMPLETION PLUE AND AGANDON TOTLE OF LITER CASING EMARCE PLANS COMPLETION COMPLETION TOTHEA COMPLETION Completion Completion Tother Completion Completion	^{16.} Check	Appropriat	e Box To Indicate N	ature of Norice Repo	or Orly			
TEMPERATILY ADARDON FLUE AND ALLADON Value of Altron Casine EMANCE PLANS CONVENCE DBILLING OPHS. OTHER Completion X OTHER Completion X 17. Descrite Processed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed works between the start state. Moved in service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test 0K. Ran logs and perforated zone 3254'-78', 3283'-94' W/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 630 MCFD 24 hours.								
TEMPERATILY ADARDON FLUE AND ALLADON Value of Altron Casine EMANCE PLANS CONVENCE DBILLING OPHS. OTHER Completion X OTHER Completion X 17. Descrite Processed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed works between the start state. Moved in service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test 0K. Ran logs and perforated zone 3254'-78', 3283'-94' W/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 630 MCFD 24 hours.					()		1 1	
Public of Altren Casing Change Plans Casing TEST AND CEMENT Job OTHER Completion 17. Describe Proceeded or Completed Operations (Clearly state all pertinent derails, and give pertinent ders, including estimated date of stanting any proposed work) See Rule 1153. Moved in service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test 0K. Ran logs and perforated zone 3254'-78', 3283'-94' w/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.	<u></u>		PLUG AND ABANDON					
Completion Completion Completed Operations (Clearly state all periment details, and give pertiment dates, including estimated date of storing any proposed and perforated zone 3254'-78', 3283'-94' w/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer set at 50 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000 % of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.	<u>}</u>		CHANGE PLANS		. [-]	PLUGAN	ABANDONMENT	
 ¹⁷. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dutes, including estimated date of starting any proposed work) set Rule 1163. ¹⁷. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dutes, including estimated date of starting any proposed work) set Rule 1163. ¹⁷. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dutes, including estimated date of starting any proposed work) set Rule 1163. ¹⁷. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dutes, including estimated date of starting any proposed and performance of the perturbation of						ion	X	
<pre>wok) see Rule 103. Moved in service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test 0K. Ran logs and perforated zone 3254'-78', 3283'-94' w/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.</pre>	OTHER						•	
Moved in service unit 7-14-78. Tested casing with 1000# for 30 minutes. Test OK. Ran logs and perforated zone 3254'-78', 3283'-94' w/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.	17. Describe Proposed or Completed (Operations (Cle	arly state all pertinent deta	zils, and give pertinent dates	, including c	stimated date of si	tarting any proposed	
and perforated zone 3254'-78', 3283'-94' w/2DPJSPF. Ran 2 3/8 tubing, packer, and 150' tailpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.	·	7 1/1 70	Tostad anating	1+1- 3000 / .C., 00		T		
<pre>tallpipe. Spotted perfs with 42 gallons of 7 1/2% MSR 150 acid and washed and soaked perfs. Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.</pre>	and porforated zone 2	7-14-78. 2511 701	lested casing w	1th 1000# for 30 m	minutes.	Test OK. F	Ran logs	
Pulled 2 joints of tubing and packer set at 3087'. Tubing sat at 3242'. Acidized perfs with 4000 gallons 7 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.	tailpipe. Spotted per	154 -70 , fs with A	203-94 W/ZUP 2 да]]орс оf 7]	JSPF. Ran Z 3/8 ti /2% MSP 150 poid :	ubing, p	backer, and	150'	
With 4000 gallons / 1/2% MSR 150 acid, 5000 SCF nitrogen, 7 barrels of 2% KCL water, and 7000 SCF nitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.	Pulled 2 joints of tu	hing and	packer set at 30	87' Tubing cat a	d HU WdSI + 20401	led and soak	kea perts.	
<pre>7000 SCF hitrogen. Shut in 30 minutes. Opened and flowed to pit. Swab tested well. Pulled tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.</pre>	with 4000 gallons 7 1	/2% MSR 1	50 acid. 5000 SC	F nitrogen 7 har	role of	2% KCL wate	veris	
<pre>tubing and packer. Ran tubing to 3222'. Frac well with 4000 gallons 7 1/2% MSR 150 acid and 1000 CF nitrogen per barrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.</pre>	7000 SUF nitrogen. Sh	ut in 30 r	minutes. Opened	and flowed to nit	t Swah	tastad wall	Dullad	
<pre>1000 CF Hitrogen per Darrel, 55,000 gallons of gelled KCL water, 15,000# of 100 mesh sand, 38,000# 20/40 sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.</pre>	Lubing and packer. Rai	n tubing :	to 3222'. Frac w	ell with 4000 gal	lons 7 l	/2% MSR 150) acid and	
<pre>38,000# 20/40 Sand, and 15,000# 10/20 sand. Flushed with gelled KCL water and 33% CO2. Shut in 2 hours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. 0 B0 and 0 BW and 630 MCFD 24 hours.</pre>	Toolo of nitrogen per l	barrei, 58	5,000 gallons of	gelled KCL water.	. 15.000)# of 100 me	sh sand.	
In 2 nours. Flow tested to pit. Released service unit 7-20-78. Completed well 7-26-78 as flowing gas well. O BO and O BW and 630 MCFD 24 hours.	38,000# 20/40 sand, at	nd 15,000#	# 10/20 sand. F1	ushed with gelled	KCL wat	er and 33%	CO2 Shut	
O BO and O BW and 630 MCFD 24 hours.	in 2 nours. Flow test	ed to pit.	. Released servi	ce unit 7-20-78. (Complete	d well 7-26	5-78 as	
•	llowing gas well.				·			
•	0 BO and 0 BW	and	1 630 MCFD 24 ho	urs.				
•								
•								
•								
			•					
		<u></u>						
	l'and a	1' 1	- .					

NUNED_ Kay W. Cox	Administrative Supervisor	DATE 8-4-78
Urage agaed by	TITLE	AUG 17 1978
ONDITIONS OF APPROVAL GOLOGIER 0+5-NNOCC, 1-Div 1-Susp 1-RC		