N OF COPIES RECEIV	ED	4				Form C-103 Supersedes	Old
DISTRIBUTION		┥	IEW NEVICO OF CO	SEEDVATION OO	muccion	C-102 and C	:-103
ANTA FE		-} ^	IEM WEXICO OIL COI	NSERVATION CO	MMISSION	Effective 1-	1-65
FILE		-				Sa. Indicate Ty	ne of Lease
J.S.G.S.		-				State State	Fee X
AND OFFICE		4				5. State Oil & C	
PERATOR	1					5. State 6 6	
(DO NOT USE TH			S AND REPORTS OF		NT RESERVOIR.		
. OIL X	GA5		The World Carlot Control	och vice objects.		7. Unit Agreeme	ent Name
Name of Cherator	*CLL	OTHER-				8. Farm or Lea	se liame
hapman # Schn	-14 & A	res				Weelwert	
. Address of Operator	aract					9. Weli Nc.	
	- £ Gaa 9	arriage.	Inc., Box 763,	Nobbe N M	88240	9	
Location of Well	9 4 463 9	erarces,	IME., BUX 703,	isobba, it is	00240	13. Field and F	ool, or Wildcat
	1 1	450	South		990	Langlie !	lattle
UNIT LETTER	<u> </u>	FE.	ET FROM THE South	LINE AND	FEET FRO	7777777 [~]	
THE East	LINE, SECT	10N	TOWNSHIP	RANGE	36E NMP1		
	777777	15	. Elevation (Show wheth	er DF, RT, GR, etc.	.)	12. County	
				95.7 GR		Les	
r. N		Appropriation	e Box To Indicate то:	Nature of Noti	_	Other Data	::
					. 11	ALTE	RING CASING
PERFORM REMEDIAL WO	чк 🔲		PLUG AND ABANDON	_ REMEDIAL WORK			
PERFORM REMEDIAL WOF Temporarily abandon	* k		PLUG AND ABANDON	COMMENCE DRIL	LING OPNS.	PLUG	AND ABANDONMENT
	**		PLUG AND ABANDON	COMMENCE DRIL	D CEMENT JOB	PLUG	AND ABANDONMENT
TEMPORARILY ABANDON	RK		_	COMMENCE DRIL	₩	PLUG	AND ABANDONMENT
TEMPORARILY ABANDON FULL OR ALTER CASING OTHER	or Completed	Operations (Cle	_	COMMENCE DRIL CASING TEST AN OTHER	D CEMENT JQB		
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Froposed	or Completed of 103. Spud 5:0 at 1197 per sack 4# floce 5:30 PM	0 AM 4/16 with 350 amd 250 le per se	/78. Cemented sacks Class "C' ck. Circulated WOC 18 hours,	commence Drill casing test an other details, and give per 8 5/8" 24# 67 gel, 4", 57 gel, 4 calciud 100 sacks.	J-55 casing flecele chloride, Plug down		
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Froposed Work) SEE RULE	or Completed of 103. Spud 5:0 at 1197 per sack 4# floce 5:30 PM for 30 m	0 AM 4/16 with 350 and 250 le per sa 4/16/78. inutes, t	/78. Cemented sacks Class "C' ck. Circulated WOC 18 hours,	commence DRIL casing Test an other details, and give per 8 5/8" 24# 4", 67 gel, 4", 2% calcium 100 sacks. test casing	J-55 casing flecele chloride, Plug down with 700#	ng estimated date o	starting any propose
TONED ACTOR CASING OTHER 7. Describe Frogosed work) SEE RULE	or Completed of 103. Spud 5:0 at 1197 per sack 4# floce 5:30 PM for 30 m	0 AM 4/16 with 350 and 250 le per sa 4/16/78. inutes, t	778. Cemented sacks Class "C'sacks Class "C'ck. Circulate WOC 18 hours, est O.K.	commence DRIL casing Test an other details, and give per 8 5/8" 24# 4", 67 gel, 4", 27 calciud 100 sacks. test casing	J-55 casing flecele chloride, Plug down with 700#	ng estimated date o	f starting any propose
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Froposed Work) SEE RULE	or Completed of 103. Spud 5:0 at 1197 per sack 4# floce 5:30 PM for 30 m	O AM 4/16 with 350 and 250 le per sa 4/16/78. inutes, t	778. Cemented sacks Class "C'sacks Class "C'ck. Circulate WOC 18 hours, est O.K.	commence DRIL casing Test an other details, and give per 8 5/8" 24# 4", 67 gel, 4", 2% calcium 100 sacks. test casing	J-55 casing flecele chloride, Plug down with 700#	ng estimated date o	starting any propose