

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM-7488
2. NAME OF OPERATOR Amoco Production Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 4072, Odessa, TX 79760	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL x 1980' FWL, Sec. 9 (Unit N, SE/4, SW/4)	8. FARM OR LEASE NAME Myers "B" Federal
14. PERMIT NO.	9. WELL NO. 32
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3268' RDB	10. FIELD AND POOL, OR WILDCAT Langlie Mattix Queen
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 9-24-37 9-24-37
	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Purpose: to permanently plug and abandon subject well. MI and RUSU and circulate 5 1/2" casing with 10 pound brine with 25 pound/BBI gel and pull tubing. Run CIBP on wireline and set at 3150' and cap with 35' Class C cement. Run tubing to 2300' and spot 50 sacks

- ① Class C cement in 5 1/2" casing from 1900' to 2300' and pull tubing. Run 3-1/8" casing guns and perforate from 400' to 401' with 4 SPF. Pump down 5 1/2" casing and establish circulation and pump 175 sx Class C cement and circulate cement to surface through 8-5/8" - 5-1/2" annulus. Dig out cellar and cut off wellhead. Cap well and install PXA marker. RD and MOSU.

① would rather have 100' plug across csg shoe (8 5/8")
② no need to perf 5 1/2" and circ. ann. to surf
... Since no open borehole extends to surf. via annulus.

(915) 367-3800



18. I hereby certify that the foregoing is true and correct

SIGNED O. M. Mitchell TITLE Sr. Admin. Analyst

DATE 10/26/87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 11-18-87

*See Instructions on Reverse Side