Submit 3 Copies To Appropriate Dis	Copies To Appropriate District State of New Mexico		Form C-103	
Office District I  Energy, Minerals and Natural Resources		Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	
1301 W. Grand Avenue, Artesia, NM 87210 OIL CONSERVATION DIVISION			30-025-26074 5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X	
District IV Santa Fe, NM 8/505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  PROPOSALS.)  1. Type of Well:			7. Lease Name or Unit Agreement Name: PHILLIPS—GOLDSTON	
Oil Well Gas Well Other  2. Name of Operator			0.17.11.51	
NORTHEAST LOOP GAS COMPANY, L.P.			8. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
P.O. BOX 25204, DALLAS, TEXAS 75225			JALMAT Tansil-Yates-Seven Rivers	
4. Well Location				
Unit Letter G: 2310 feet from the North line and 1980 feet from the East line				
Section 26	Township 24S	Range 36E	NMPM	County Lea
	10. Elevation (Show wheth			
3324 RKB				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK ALTERING CASING				ORT OF: ALTERING CASING
TEMPORARILY ABANDON				
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB		ADANDONWENT
OTHER:		OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
9-18-02 - Pull tubing and rods. Drop standing valve and test casing for 15 minutes @ 3500 psi. Clean out 82 feet of fill.				
9-19-02 - Perferate 16 holes between 2714 - 2730 and 16 holes between 2740 - 2756. Break down perferated zones with 1500 gallons of 15% NEFE HCL acid.				
9-20-02 - Circulate hole and swab. Return well to production.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE	Afan TITI	E President	·	DATE 9/17/02
Type or print name DAV	ID A. HART		Telenho	(214) one No. 522–6646
(This space for State use)			reichno	
0.01	GINAL SIGNED BY TITI	_		SEP 18 2002
APPPROVED BY Conditions of approval iGAR	TITLEY W. WINK	.E		DATE
Conditions of approval, if ARY W. WINK OC FIELD REPRESENTATIVE IL'STAFF MANAGER				