Submit 3 Copies
to Appropriate
District Office

<u>DISTRICT </u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION				
2040 Pacheco St. <u>DISTRICT II</u> Santa Fe, NM 87505			WELL API NO. 30-025-26195	5	
P.O. Drawer DD, Artesia, NM 88210			sIndicate Type of Le		
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			State Oil & Gas Le		
			B-934	aso NU.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
I DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7Lease Name or Un New Mexico "A	nit Agreement Name	
(FORM C-101) FOR SUCH PROPOSALS.)			New Mexico A	D State	
OIL GAS WELL CONTRACT CAS	OTHER				
² Name of Operator John H. Hendrix Corporation			sWell No. 4		
3Address of Operator P. O. Box 3040, Midland, TX 79702-3040			Pool name or Wildo		
Well Location			Langlie Mattix 7	7 RG & Fowler U. Yeso	
Unit Letter :660 Fee	t From The North	Line and 660	Feet From The	EastLine	
Section 16	Township 24S	Range 37E	NMPM	Lea County	
	Development (Show whether DF, Weight Strength	RKB, RT, GR, etc.)			
¹¹ Check Appro	priate Box to Indicate N	ature of Notice Per	ort or Other I		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
		REMEDIAL WORK			
	CHANGE PLANS	COMMENCE DRILLING OF			
PULL OR ALTER CASING		CASING TEST AND CEME			
OTHER:					
OTHER: P&A LMSRQ & repair csg. on Fowler Upper Yeso					
This well was drilled by Exxon and had 4-1/2" x 2-7/8" cemented in a 9-1/2" hole to 3746' and a 7-7/8" hole to 5797'. The 2-7/8" was set at 3618' and the 4-1/2" at 5797'. Cement top is approximately 2050'. This well has been TA'd since taking over from Exxon. It was determined that there was communications between the 4-1/2" and the 2-7/8" at expressions between the 4-1/2" and the 2-7/8" and the 2-7/8" at expressions between the 4-1/2" and the 2-7/8" at expressions between the 4-1/2" at 5797'.					
that there was communications between the 4-1/2" and the 2-7/8" at approximately 3100'. To repair the leak in the 4-1/2" it was decided to P&A the 2-7/8" tubing and squeeze the 4-1/2". This was accomplished by doing the following:					
2/12/98 Set RBP in 4-1/2" above Yeso perfs.					
2/16/98 Set CICR at 3000' in 4-1/2" csg. Cemented w/ 300 sx. Class "C" w/ 2% CaCl. Circ. 42 sx. up 2-7/8" tbg. to pit. Closed in 2-7/8" tbg. to pit. Closed in 2-7/8"					
tbg. and squeezed 150 sx. between 4-1/2" csg. & 2-7/8" tbg. Obtained 1300 psig squeeze. Sting out of CICR and reversed out 3-1/2 bbls. to pit.					
2/17/98 Drilled out CICR and cement.	Tested csg. to 560#. OK.				
Langlie Mattix Seven Rivers Queen from 2-7/8" tbg. is now P&A.					
We have run tbg., rods and installed PU to test Yeso fr. the 4-1/2" csg.					
I hereby certify that the promation above is true and complete to the best of my knowledge and belief.					
SIGNATURE KENNIG A.	1 Melsech	LE Vice President		02.07.00	
TYPE OR PRINT NAME RONNIE H. Westbrook	·····			DATE 02-27-98	
(This space for State Use)				TELEPHONE NO. (915) 684-6631	
ODIONAL CONTD BY	CHRIS WILLIAMS				
APPROVED BY	TITL	.E		DATE	

CONDITIONS OF APPROVAL, IF ANY:

JC

2A Landhie Mattin

dis