

STATE OF NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

> POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

November 6, 2000

Occidental Permian LP ATT: Mark Stephens P 0 Box 4294

Houston TX 77210

RE: REQUIRED GAS\OIL RATIO TEST

Gentlemen:

Your company has put <u>South Mattix Unit</u> #38y-A, 15-24s-37e API #30-025-26730 back on production and in doing so the Oil Conservation Division needs some more paper work to bring your well file up to date.

After a well has been put back on production a Gas\Oil Ratio Test is required to reassign your allowable to the well. You may put this test on the C-104 also stating your current transporters for the well. The C-104 has been revised February 10, 1994 because of the new ONGARD computer system. We have enclosed some copies of this form.

If you have any questions on this matter, please call the District I, Hobbs office (505) 393-6161.

Very truly yours.

OIL CONSERVATION DIVISION

Chris Williams; Supervisor, District I

JS:dp cc:file