

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

CONSERVATION  
SANTA FE State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Highland Production Company	8. Farm or Lease Name Double "SS"
3. Address of Operator P. O. Box 6326, Odessa, Texas, 79762	9. Well No.
4. Location of Well UNIT LETTER <u>C</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>24-S</u> RANGE <u>36-E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Jalmat</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3293.1 GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 8 5/8" Casing in 12 1/4" hole @ 1214 Feet. Cement with 200 sacks - Circulated.  
Wait 12 hours - test 800 lbs. - 15 minutes.

Set 4 1/2" Casing in 7 7/8" hole @ 3295 '. Cement with 510 sacks - Wait 12 hours.  
Test 800 lbs. - 15 minutes. Rig Pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

HIGHLAND PRODUCTION COMPANY

SIGNED Marvin T. Smith TITLE President DATE April 16, 1984

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 24 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
APR 23 1984  
O.C.D.  
HOBBS OFFICE