


ASE ROTARY TABLE

Flow line will have to be made
to fit UNDER Rotary.



RECEIVED

AUG - 8 1985

100-100000-100000

