Form 3160-5 (November 1994)

## **UNITED STATES**

N.M. Oil Cons. Division FORM APPROVED

OMB No. 1004-0135 1625 N. French Dr. DEPARTMENT OF THE INTERIOR Expires July 31, 1996 BUREAU OF LAND MANAGEMENT Hobbs, NM 88240 ease Serial No. SUNDRY NOTICES AND REPORTS ON WEL NMLC032339A Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side Type of Well ☑ Oil Well ☐ Gas Well ☐ Other Well Name and No. G H MATTIX B #1 2. Name of Operator 9. API Well No. SAGA PETROLEUM LLC 30-025-31770 3b. Phone No. (include area code) 3a. Address 415 W WALL, STE 1900, MIDLAND, TX 79701 (915)684-4293 10. Field and Pool, or Exploratory Area Teague Paddock-Blinenry 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 460' FNL & 1980' FWL Sec. 3 (C) T24S, R37E 11. County or Parish, State LEA, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Deepen ☐ Water Shut-Off Acidize Production (Start/ Resume) ☐ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other ADD PERFS ☐ Subsequent Report Casing Repair **New Construction** Recomplete Plug and Abandon Change Plans Temporarily Abandon ☐ Final Abandonment Notice Convert to Injection ☐ Plug Back ☐ Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) TIH to 5255', set RBP, set pkr @ 5233', test plug to 500 psi, good, release pkr, circ hole w/150 bbls 2% KCL, PU to 5183', spot 150 gal 15% NEFE inhib acid. POOH to 3523' to swab, rec 80 bbls FFL 2500', POOH & LD swab. 7-21 Perf from 5142'-49', 5155'-59', 5162'-63', 5178'-82' 7-22 Cont to TIH w/pkr to RBP, set pkr & test plug to 1000 psi, good. PU to 5072', set pkr, test BS to 500 psi, csg test good. RU swab, IFL 600', rec 18 BW. 8-15 Well produced 4 BO & 148 BW, FL 148 JFS 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title **Bonnie Husband Prod Analyst** Date Signature 08/15/2000 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Date

Well Completion Or Recompletion Report And Log (Form 3160-4) Required For The Paddock.

Office ot warrant or ıbject lease

1 willfully to make to any department or agency of the United States any false, fictitious or

A Alle State the Converse to t

RECEIVED

AUG 17 2000

BLM

ROSWIT