

CONTINGENCY AND EVACUATION PLAN

Dusty Mac Resources Inc.
Madera "24" Federal Well No. 1
Lea County, New Mexico

C. Emergency Procedures and Definitions of Warning Signs:

Condition: GREEN - Normal Operations

Condition: YELLOW - Potential Danger -- CAUTION

Cause for Condition:

1. Circulating
2. Trip gas after trips
3. Circulating out gas through choke
4. Poisonous gas present, but below threshold concentration

Condition: RED - Extreme Danger

1. Uncontrolled well
2. Poison gas present above threshold levels

Safety Action:

1. Check safety equipment and keep it with you
2. Do not panic
3. The decision to ignite the well should be made only as a last resort and it is clear that:
 - a. Human life is endangered, and
 - b. There is no hope of controlling the well under prevailing conditions. Every effort should be made to notify office - if time permits.
4. Order evacuation of local people within the danger zone. Request help from local authorities, (State Police and Sheriff's Department) to evacuate people and to control traffic.
5. Notify office of well condition.

RECEIVED

MAR 30 1994

LIBRARY
HONOLULU