

CONTINGENCY AND EVACUATION PLAN

Dusty Mac Resources Inc.
Madera "24" Federal Well No. 1
Lea County, New Mexico

Definition of Warning Signs: (Cont'd)

1. Uncontrollable well. (Cont'd)
 - A. Two persons, if available, re-enter hazardous area with air packs and each attached to an assistant via safety line. The assistant shall also be wearing respiratory equipment but outside of the hazard area.
 - B. Locate and evacuate all other persons in hazardous area to safety briefing area.
 - C. Proceed with emergency first aid to all injured. Call hospital emergency ward. Alert them of the problem and have them send rescue vehicle immediately.
2. Locate, define problem and proceed with emergency shut-in procedures per Company's Blowout Drill Procedure.
3. Stay in "safe briefing area" unless instructed to do otherwise.
4. Only enter hazardous area with adequate air supply and attended by someone with a safety rope.