

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

| | |
|---|--|
| WELL API NO. | 30 025 32569 |
| 5. Indicate Type of Lease | STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil / Gas Lease No. | |
| 7. Lease Name or Unit Agreement Name | COOPER JAL UNIT |
| 8. Well No. | 407 |
| 9. Pool Name or Wildcat | JALMAT |
| 10. Elevation (Show whether DF, RKB, RT,GR, etc.) | GR-3314' |

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. Type of Well: | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> |
| 2. Name of Operator | TEXACO EXPLORATION & PRODUCTION INC. |
| 3. Address of Operator | 205 E. Bender, HOBBS, NM 88240 |
| 4. Well Location | Unit Letter <u>J</u> : <u>2540</u> Feet From The <u>SOUTH</u> Line and <u>1640</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>24-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY |
| 10. Elevation (Show whether DF, RKB, RT,GR, etc.) | GR-3314' |

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | | | |
|-----------------------|--------------------------|------------------|--------------------------|
| PERFORM REMEDIAL WORK | <input type="checkbox"/> | PLUG AND ABANDON | <input type="checkbox"/> |
| TEMPORARILY ABANDON | <input type="checkbox"/> | CHANGE PLANS | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | OTHER: | <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | | | |
|-----------------------------|--------------------------|----------------------|-------------------------------------|
| REMEDIAL WORK | <input type="checkbox"/> | ALTERING CASING | <input type="checkbox"/> |
| COMMENCE DRILLING OPERATION | <input type="checkbox"/> | PLUG AND ABANDONMENT | <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB | <input type="checkbox"/> | OTHER: | <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-26-96 MIRU PRIDE WS TOH W/ RODS & PUMP. INSTALL BOP & POH W/ TBG. SDFN
7-27-96 RU HALIB. WL RUN GR-CCL 3683-2800 TOH.TIH W/ 5-1/2 CIBP & SET 3350.TOH TIH W/ BAILER & DUMP 10' CMT ON TOP OF PLUG
TOH.PBTD=3340'.TIH W/ 4" CSG. GUN 120 DEGREE PHASING 4JSPF .46 " HOLE & PERF 5-1/2 CSG JALMAT ZONE 3036-3114. 40' NET 160
HOLES.TOH RD HALIB. WL TIH W/ 5-1/2 RBP W/ BALL CATCHER & PKR ON 2-7/8 TBG. TESTED TO 5000# BY PHIL'S. SET RBP @ 3131' PULL UP
& SET PKR 2965. SDFN
7-28-96 SD
7-29-96 BY DOWELL PICKLE TBG & REVERSE OUT. PRESSURE BACKSIDE TO 500#.THENACIDIZE JALMAT CSG PERFS 3036-3114 W/ 3000
GALS 15% NE FE HCL W/ 240 7/8 BALLS.MAX PRESS=1200#, MIN PRESS=550#, 400# INCREASE W/ BALLS,AIR=7.5BPM,ISIP=150#, VACUUM IN 1
MIN.RIG UP SWAB STARTING FLUID LEVEL 1700'. SWAB 3 HRS RECOVERED 50 BBLS LOAD. ENDING FLUID LEVEL 2400'. RD SWAB UNSET
7-30-96 TBG SET @ 3227',SN=3187',TAC=2950.REMOVE BOP & NU WELL HEAD.TIH W/ 2-1/2 X2"X20" PUMP.8-1-1/2 SINKER BARS,44-3/4,43-7/8,33-
1" RODS HUNG ON RDMO.
7-31-97 NO TEST
8-1-96 NO TEST
8-02-96 thru 8-26-96: Testing.
8-27-96; 24 HR TEST POB 47-BO 54-BW 17-MCF OPT LAST REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 9/9/96
TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use) ORIGINAL SIGNED BY JERRY BAXTON
DISTRICT I SUPERVISOR

APPROVED BY JERRY BAXTON TITLE DISTRICT I SUPERVISOR DATE SEP 12 1996
CONDITIONS OF APPROVAL, IF ANY: