Submit 3 copies to Appropriate District Office

APPROVED BY_

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico

Eng. 4. Minerals and Natural Resources Department

Form C-103 Revised 1-1-8

District Office	Revised 1-1-89
OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30-025-32892
DISTRICT II	
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE FEE FEE
DISTRICT III	
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT	· ·
(FORM C-101) FOR SUCH PROPOSALS.)	COOPER JAL UNIT
1. Type of Well: OIL GAS OTHER	
Well - Office	0.14/ #.4/
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	8. Well No. 412
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	9. Pool Name or Wildcat
4. Well Location	LANGLIE MATTI/JALMAT YATES 7R QUEEN
	Feet From The EAST Line

Section 24 Township 24-S Range 36-E NM	PMLEA_ COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report	. or Other Data
1	BSEQUENT REPORT OF:
	BSEQUENT REPORT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPER	RATION PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMEN	T JOB
OTHER:	
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinen any proposed work) SEE RULE 1103. 12-22-97: MIRU. INSTL BOP. PULL TBG. 12-23-97: RAN GAUGE RING TO 3450'. GAUGE RING STUCK IN SCALE. RAN OVERSHOT TO 3430' SCALE. 12-24-97: RAN SHOE, FLOAT SUBS, BAILER. C/O FR 3430-3473'. RAN OVERSHOT. TAG @ 3473'. PS 35' CMT 3445-3410'. (NEW PBTD) 12-27-97: RAN SONIC HAMMER ON TBG. CLN PERFS 3016-3100' W/200 BBLS 2% KCL FRESH WAT 15% NEFE THRU SONIC HAMMER. FLSH W/18 BBLS 2% KCL FRESH WATER. RAN MUD ANCHOR, 	OVERSHOT PACKED W/CARBONATE SH JUNK TO 3526'. SET CIBP @ 3445'. DMPD ER. ACIDIED PERFS 3016-3100 W/2000 GALS
3228°. TA @ 2921°. 12-28-97: RAN GAS ANCHOR ON PMP. PRESS TBG TO 500#, OK. RD. ON PRODUCTION @ 3:00 PM 12-29-97: CHANGED MOTOR SHEAVE TO SLOW DOWN PUMPJACK. ON PRODUCTION @ 10:00 AM 12-30/1-14-98: TESTING 1-14-98: ON 24 HR OPT ENDING 10:00 AM. PUMPED 36 BO, 216 BW, & 9 MCFPD. CHANGE STATU	м. м.
I hereby certify that the information about is true and complete to the best of my knowledge and belief.	
SIGNATURE A WINUS PURCE TITLE Engineering Assistant	DATE 1/20/98
TYPE OR PRINT NAME J. Denise Leake	Telephone No. 397-0405

□**NJAN** 2 8 2002