

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32892
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	COOPER JAL UNIT
8. Well No.	412
9. Pool Name or Wildcat	JALMAT; TAN-YATES 7 RIVERS/LM

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>P</u> : <u>980</u> Feet From The <u>SOUTH</u> Line and <u>225</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>24-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	GR-3295'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☒ Add Jalmat perms & acidize

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-13-96 MIRU PRIDE WS FISH ROD PART @ ? . TOH W/RODS & PUMP, INSTALL BOP, TOH W/2-7/8" TBG.
 9-14-96 SHUT DOWN
 9-15-96 SHUT DOWN
 9-16-96 RU HALIB. WL. & PERF. 5-1/2 CSG. JALMAT ZONE 4 JSPF W/ 4 CSG. 3016-3283. 79' NET, 316-.45" HOLES. TOH W/ TBG. & TOOLS & LAY DOWN PERF. GUN. TIH W/ RBP & PKR. SET RBP @ 3300' TESTED TBG. IN HOLE TO 5000#. LEFT PKR SWINGING 2950' SDFN
 9-17-96 SET PKR & 2957 RU DOWELL & PICKLE TBG. W/ 300 GALS 15% NE FE HCL & 150 GALS XYLENE. LOWER PKR. TO 3115 & SET. THEN ACIDIZE 5-1/2 JALMAT PERFS 3131-3283 W/ 3000 GALS 15% NE FE HCL & 190 7/8 BALLS. MAX. PRESS=2250#, MIN PRESS=1149#, AIR=8.1 BPM ISIP=VACUUM. RESET RBP & 3080'. PULL PKR. TO 2987. THEN ACIDIZE 5-1/2 JALMAT CSG PERFS. 3016-3074 W/ 3000 GALS 15% NE FE HCL & 280 7/8 BALLS, MAX PRESS=2250#, MIN PRESS=800#, AIR=8BPM, ISIP=VACUUM. RU SWAB. SWABBED DRY IN 5 RUNS RECOVERED 13 BBLS LOAD. RD SWAB. RELEASE PKR. & LOWER TO 3080'. RELEASE RBP & TOH W/ TBG. & TOOLS. TIH W/ 2-7/8 KNOTCHED COLLAR & BULL DOG BAILER & TAG 3530. CLEAN OUT TO 3535. PULLING UNIT BROKE DRIVE CHAIN SDFN
 9-18-96 W/ BULLDOG BAILER CLEAN OUT 3534-3590. BAILER STOPPED WORKING. TOH CLEAN OUT BAILER, C/O KNOTCHED COLLAR. TIH W/ BAILER CLEAN OUT 3590-3608. BAILER QUIT. TOH & CLEAN OUT. SDFN
 9-19-96; TIH W/ SAME BAILER & 4-3/4 BLADE BIT TAG 3608 CLEAN OUT SAND TO 3717-PBTD. POH W/ TBG & TOOLS CLEAN OUT BAILER TAG IN AM SDFN
 9-20-96; TIH W/ 3-1/2 OPSMA, SN TBG. TBG. SET @ 3057'. REMOVE BOP & NU WELLHEAD. TIH W/ PUMP, HUNG ON, RDMO PUMPED UP 5:00PM
 9-21-96 PUMPING & TESTING
 10-23-96; PUMPED ON BEAM 24 HRS RECOVERED-41-BO 250-BW 12-MCF. (DHC JALMAT & LANGLEIE MATTIX). OPT LAST REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 11/5/85
 TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use)

APPROVED BY DISTRICT SUPERVISOR TITLE DATE NOV 19 1986
 CONDITIONS OF APPROVAL, IF ANY: