

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35141
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.</p>		7. Lease Name or Unit Agreement Name FANNING "4"
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	8. Well No. 1
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	9. Pool Name or Wildcat UNDESIGNATED DEVONIAN	
<p>4. Well Location</p> <p>Unit Letter <u>B</u> : <u>879</u> Feet From The <u>NORTH</u> Line and <u>2078</u> Feet From The <u>EAST</u> Line</p> <p>Section <u>4</u> Township <u>24-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY</p>		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3272'</u>		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>		
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>		
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	PRODUCTION CASING <input checked="" type="checkbox"/>		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-20-00/11-22-00: RAN 100 JTS 5 1/2" CSG. SPOT 100 BBLs OIL TO WRK STUCK CSG. RUN FREE POINT. STUCK @ 2491-2493 DV TOOL. WRK CSG FREE. RAN 177 JTS 5 1/2" CSG WSH 140' TO BTM. CMT W/2000 SX 35/65 POZ 125 SX 50/50 POZ. RELEASED RIG @ 13:00 HRS 11-21-00.

Cmt Gflashset - Cmt inside CSG from Surface To T.D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 11/23/00

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED [Signature] TITLE Geologist DATE FEB 21 2001

CONDITIONS OF APPROVAL, IF ANY: _____