

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 02875
7. Unit Agreement Name
8. Farm or Lease Name Anderson
9. Well No. 3
10. Field and Pool, or Wildcat Allison Penn
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Eugene E. Nearburg
3. Address of Operator 4219 Sigma Road Dallas, Texas 75240	4. Location of Well UNIT LETTER J 1980' FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 8 South RANGE 37 East NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4040.9' Gr.	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 25 sx. plug from T.D. to 9253' (Perfs. at 9558 to 9580')

Cut 4 1/2" casing at approx. 7675' and pull.

Spot 25 sx plug at 4 1/2" stub.

Spot 25 sx plug at 7 5/8" shoe 4188'.

Spot 10 sx plug at surface and set dry hole marker.

Work to start 4-14-71.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie J. Selwick	TITLE Production Supt.	DATE 4-12-71
APPROVED BY JR [Signature]	TITLE SUPERVISOR DISTRICT	DATE APR 23 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 22 1971

OIL CONSERVATION COMM.
HOBBS, N. M.