ENVIROTECH Inc.

5796 US HWY. 64, FARMINGTON, NM 87401
(505) 632-0615

PA 028

COC # 2786

FIELD REPORT: SITE ASSESSMENT

JOB No: 93163
PAGE No: 1 of 1

PROJECT: P.I. ASSESSMENTS
CLIENT: PHILLIPS
CONTRACTOR: ENVIROTECH, INC.
EQUIPMENT USED: JCB EXTENDAHOE

DATE STARTED: 7-7-93
DATE FINISHED: 7-7-93
ENVIRO. SPCLT: RES
OPERATOR: CIMARRON
ASSISTANT:

LOCATION: LEASE SAN JUAN 30-5 WELL: # 83 DK QD: 950' FWL, 1480' FSL (L)
SEC: 23 TWP: 30 N RNG: 5 W PM: NM CNTY: R.A. ST: NM PIT: SEP.

LAND USE: RANGE - CARSON NAT'L FOREST - LEASE # SF 078738
SURFACE CONDITIONS: EARTHEN PIT - DRY -

FIELD NOTES & REMARKS: PIT IS LOCATED APPROX. 55 FEET N. 15° E. OF WELLHEAD
CLOSURE STD: < 1000 ppm TPH
T1: MOIST, BROWN/YELLOW, POORLY GRADED SAND. NO ODOR.

RANK SCORE = 10

SAMPLE INVENTORY		
SMPL ID:	SMPL TYPE:	LABORATORY ANALYSIS:
T1 @ 4.5'	SOIL	418.1

SCALE
0 5 10 FEET
26' x 26'

SITE DIAGRAM



TEST HOLE LOGS:

	TH#: 1	TH#:	TH#:	TH#:
	SOIL TYPE: / SMPL TYPE: / OVM/TPH	SOIL TYPE: / SMPL TYPE: / OVM/TPH	SOIL TYPE: / SMPL TYPE: / OVM/TPH	SOIL TYPE: / SMPL TYPE: / OVM/TPH
GS				
1				
2				
3				
4	PIT BOTTOM			
	SP GRAB ND			
5	TD = 4.5'			
6	SANDSTONE			
7	BEDROCK			
8				
9				
10				

SOIL TYPE: C - Clay, M - Silt, S - Sand, G - Gravel Plasticity: L - None, M - Plastic Grading: P - Poorly, W - Well