NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-29-26 Operator Catamount Energy API #30-0 45-38288


Property Name Navajo Lake 32-6-1 Well No. #1H Location: Unit I Section 10 Township 32N Range 6W

Well Status(Shut-In or (Producing)) Initial PSI: Tubing 49 Intermediate N/A Casing 51 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME					
5 min	0		51		
10 min	0		51		
15 min	0		51		
20 min					
25 min					
30 min					



FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Gauge showed 0, opened bH valve to nothing. No blowing during the 15-min test. Shut in for 5-min. Gauge was 0, opened to nothing.

By Kenny Castleberry Witness Jason Heslop NMOCD

(Position)

E-mail address _____

Received by OCD: 4/29/2026 11:35:39 AM

Released to Imaging: 9/8/2026 3:58:17 PM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 580253

CONDITIONS

Operator: CATAMOUNT ENERGY PARTNERS LLC 600 17TH STREET STE 1900 S DENVER, CO 80202	OGRID: 308973
	Action Number: 580253
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2026