

MYCO INDUSTRIES

EAGLE CREEK AREA
EDDY COUNTY, NEW MEXICO
ISOPACH MAP
CONTOURS SHOW THICKNESS OF CISCO
CARBONATE BANK
WITH READING LESS THAN 50 API UNITS ON GAMMA RAY LOG

GEOL: L.J. LAMMERS	TD > 6000'	DRAFT\A93032E
C.I. = 50'	1"=1000'	FIG. NO.6 11/93