Burlington Resources

ConocoPhillips

# Schematic - Current

## SAN JUAN 28-6 UNIT #133N

API - 30 - 039 - 30657

RCVD JUN 3 '09
OIL CONS. DIV.
DIST. 3

**Most Recent Job**

**Jobs**

| Job Category | Primary Job Type | Secondary Job Type | Actual Start Date | End Date |
|---|---|---|---|---|
| COMPLETIONS | INITIAL COMPLETION | INITIAL COMPLETION | 3/27/2009 | 5/15/2009 |

Well Config: DEVIATED - Original Hole, 5/27/2009 3:23:49 PM

| ftKB (MD) | Schematic - Actual |
|---|---|
| 15 | |
| 16 | 2-1, Casing Hanger, 7, 6.366, 15, 1.0 |
| 18 | 3-1, Casing Hanger, 4 1/2, 4.000, 15, 1.0 |
| 19 | 1-1, CASING HEAD, 9 5/8, 9.001, 15, 3.0 |
| 26 | 1-2, Casing Nipple, 9 5/8, 9.001, 18, 1.5 |
| 45 | 2-2, PUP JOINT, 7, 6.366, 16, 10.0 |
| 231 | 3-2, Casing Pup Joint, 4 1/2, 4.000, 16, 29.3 |
| 232 | 1-3, Casing Joints, 9 5/8, 9.001, 19, 211.5 |
| 237 | 1-4, SAW TOOTH COLLAR, 9 5/8, 9.001, 231, 1.0 |
| 2,790 | |
| 2,940 | 2-3, Casing Joints, 7, 6.366, 26, 2,914.1 |
| 2,943 | 2-4, Stage Tool, 7, 6.366, 2,940, 3.0 |
| 4,380 | 1-1, Tubing, 2 3/8, 1.995, 15, 7,977.3 |
| 4,389 | 3-3, Casing Joints, 4 1/2, 4.000, 45, 4,334.2 |
| 4,687 | 3-4, Marker Joint, 4 1/2, 4.000, 4,380, 10.0 |
| 4,688 | 2-5, Casing Joints, 7, 6.366, 2,943, 1,743.4 |
| 4,716 | 2-6, Float Collar, 7, 6.366, 4,687, 1.0 |
| 4,730 | 3-5, Casing Joints, 4 1/2, 4.000, 4,389, 326.3 |
| 4,731 | 2-7, Casing Joints, 7, 6.366, 4,688, 42.1 |
| 4,742 | 2-8, Float Shoe, 7, 6.366, 4,730, 1.0 |
| 4,799 | 3-6, Casing Joints, 4 1/2, 4.000, 4,716, 83.1 |
| 5,208 | |
| 5,574 | Perforated, 5,208-5,574, 4/17/2009 |
| 5,758 | |
| 6,170 | PERFORATED, 5,758-6,170, 4/17/2009 |
| 7,697 | 3-7, Casing Joints, 4 1/2, 4.000, 4,799, 2,897.9 |
| 7,707 | 3-8, Marker Joint, 4 1/2, 4.000, 7,697, 10.0 |
| 7,894 | |
| 7,992 | PERFORATED, 7,894-8,082, 4/16/2009 |
| 7,994 | 1-2, Tubing Pup Joint, 2 3/8, 1.995, 7,992, 2.0 |
| 8,025 | 1-3, Tubing, 2 3/8, 1.995, 7,994, 30.9 |
| 8,026 | 1-4, Profile Nipple, 2 3/8, 1.785, 8,025, 1.1 |
| 8,028 | 1-5, Mule Shoe W/exp-chk, 2 3/8, 1.785, 8,026, 1.0 |
| 8,082 | |
| 8,111 | |
| 8,111 | 3-9, Casing Joints, 4 1/2, 4.000, 7,707, 404.4 |
| 8,112 | 3-10, Float Collar, 4 1/2, 4.000, 8,111, 0.8 |
| 8,113 | 3-11, Float Shoe, 4 1/2, 4.000, 8,112, 0.8 |
| 8,114 | |





Report Printed: 5/27/2009

RV