District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-144
June 1, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒
Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Operator. Dugan Production Corp Telephone: (505)325-1821 e-mail address:
Address: P.O. Box 420, Farmington, New Mexico 87401
Facility or well name: LH No. 174 API #: 30-045-28533 U/L or Qtr/Qtr A Sec 32 T 23N R 8W
County: San Juan Latitude 36.18901 Longitude 107.69787 NAD: 1927 ☐ 1983 ☐ Surface Owner Federal ☐ State ☒ Private ☐ Indian ☐

Pit	**Below-grade tank**		
Type: Drilling ☐ Production ☒ Disposal ☐ Workover ☐ Emergency ☐ Lined ☐ Unlined ☒ Liner type: Synthetic ☐ Thickness ____mil Clay ☐ Pit Volume 77± bbl	Volume: ____bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes ☐ If not, explain why not.		
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points)	0
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points)	0
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points)	10
	Ranking Score (Total Points)		10

If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite ☒ offsite ☐ If offsite, name of facility_____. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No ☒ Yes ☐ If yes, show depth below ground surface_____ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments:
12' x 12' x 3'± deep unlined production pit, center located at approximately 105 Feet North 15° East of wellhead.
Use backhoe to collect 5-point composite sample at 8 foot depth for lab testing.
Excavate to 15' x 15' x 8' and landfarm on-site.

RECEIVED
FEB 2008
OIL CONS. DIV. DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief. **I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐, or an (attached) alternative OCD-approved plan ☐.**
Date: January 14, 2008
Printed Name/Title Jeffrey C Blagg, agent Signature Jeffrey C. Blagg

Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

Approval:
Printed Name/Title Deputy Oil & Gas Inspector, District #3 Signature Date: FEB 12 2008

30-045-28533 36.18901 x 107.69787

CLIENT: DUGAN	**BLAGG ENGINEERING, INC.** **P.O. BOX 87, BLOOMFIELD, NM 87413** **(505) 632-1199**	LOCATION NO: COCR NO: 3042

FIELD REPORT: PIT CLOSURE VERIFICATION

PAGE No: 1 of 1

LOCATION: NAME: LH WELL #: 174 TYPE: TANK
QUAD/UNIT: A SEC: 32 TWP: 23N RNG: 8W PM: NM CNTY: SJ ST: NM
QTR/FOOTAGE: 570 FNL x 645 FEL CONTRACTOR: SIERRA

DATE STARTED 10-8-07
DATE FINISHED:
ENVIRONMENTAL SPECIALIST: JCB

EXCAVATION APPROX. 15 FT. x 15 FT. x 8 FT. DEEP. CUBIC YARDAGE: 45±

DISPOSAL FACILITY: ON-SITE REMEDIATION METHOD: L.F.

LAND USE: RANGE - STATE LEASE: LH-174 FORMATION: GAL

FIELD NOTES & REMARKS: PIT LOCATED APPROXIMATELY 105 FT. N15E FROM WELLHEAD.

DEPTH TO GROUNDWATER: >100 NEAREST WATER SOURCE: >1000 NEAREST SURFACE WATER: >200

NMOCD RANKING SCORE: 10 NMOCD TPH CLOSURE STD: 1000 PPM

SOIL AND EXCAVATION DESCRIPTION:

OVM CALIB. READ. = 53.9 ppm
OVM CALIB. GAS = 100 ppm RF = 0.52
TIME: 0915 am/pm DATE: 10/8

SOIL TYPE: (SAND / SILTY SAND) / SILT / SILTY CLAY / CLAY / GRAVEL / OTHER
SOIL COLOR
COHESION (ALL OTHERS): NON COHESIVE / (SLIGHTLY COHESIVE) / COHESIVE / HIGHLY COHESIVE
CONSISTENCY (NON COHESIVE SOILS): LOOSE / (FIRM) / DENSE / VERY DENSE
PLASTICITY (CLAYS). NON PLASTIC / SLIGHTLY PLASTIC / COHESIVE / MEDIUM PLASTIC / HIGHLY PLASTIC
DENSITY (COHESIVE CLAYS & SILTS): SOFT / FIRM / STIFF / VERY STIFF / HARD
MOISTURE DRY / (SLIGHTLY MOIST) / MOIST / WET / SATURATED / SUPER SATURATED
DISCOLORATION/STAINING OBSERVED: (YES) NO EXPLANATION - STAIN on Pit Surface to 7'
HC ODOR DETECTED: (YES) / NO EXPLANATION - MOD.
SAMPLE TYPE GRAB / COMPOSITE - # OF PTS.
ADDITIONAL COMMENTS: 12'x12'x3'± cone shaped unlined PIT. USE Backhoe to Dig Into PIT & SAMPLE.

FIELD 418.1 CALCULATIONS

SAMP. TIME	SAMP. ID	LAB NO.	WEIGHT (g)	mL FREON	DILUTION	READING	CALC. (ppm)

SCALE 0 FT

PIT PERIMETER



P.D. = PIT DEPRESSION; B.G. = BELOW GRADE; B = BELOW
T.H = TEST HOLE; ~ = APPROX.; T.B. = TANK BOTTOM

OVM READING

SAMPLE ID	FIELD HEADSPACE (ppm)
1 @	
2 @	
3 @	
4 @	
5 @	
5-PT @ 8'	13

LAB SAMPLES

SAMPLE ID	ANALYSIS	TIME
5-PT	T/BTEX	1545

PIT PROFILE



TRAVEL NOTES: CALLOUT: ONSITE: 10/8/07

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified
Nonhalogenated Volatile Organics
Total Petroleum Hydrocarbons

Client:	Blagg / Dugan	Project #:	94034-010
Sample ID:	LH #174 - Tank	Date Reported:	10-10-07
Laboratory Number:	43306	Date Sampled:	10-08-07
Chain of Custody No:	3042	Date Received:	10-09-07
Sample Matrix:	Soil	Date Extracted:	10-09-07
Preservative:	Cool	Date Analyzed:	10-10-07
Condition:	Cool & Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	**4.8**	**0.2**
Diesel Range (C10 - C28)	**48.3**	**0.1**
Total Petroleum Hydrocarbons	**53.1**	**0.2**

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **Unlined Pit Closures**

Analyst

Review

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505 • 632 • 0615 • Fax 505 • 632 • 1865

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021
AROMATIC VOLATILE ORGANICS

Client:	Blagg / Dugan	Project #:	94034-010
Sample ID:	LH #174 - Tank	Date Reported:	10-10-07
Laboratory Number:	43306	Date Sampled:	10-08-07
Chain of Custody:	3042	Date Received:	10-09-07
Sample Matrix:	Soil	Date Analyzed:	10-10-07
Preservative:	Cool	Date Extracted:	10-09-07
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	**ND**	**0.9**
Toluene	**11.5**	**1.0**
Ethylbenzene	**9.7**	**1.0**
p,m-Xylene	**31.0**	**1.2**
o-Xylene	**15.4**	**0.9**
Total BTEX	**67.6**	

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	**97.0 %**
	1,4-difluorobenzene	**97.0 %**
	Bromochlorobenzene	**97.0 %**

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **Unlined Pit Closures**

Analyst

Review

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505 • 632 • 0615 • Fax 505 • 632 • 1865

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA Method 8015 Modified
Nonhalogenated Volatile Organics
Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC	Project #:	N/A
Sample ID:	10-10-07 QA/QC	Date Reported:	10-10-07
Laboratory Number:	43289	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	10-10-07
Condition:	N/A	Analysis Requested:	TPH

	I-Cal Date	I-Cal RF	C-Cal RF	% Difference	Accept. Range
Gasoline Range C5 - C10	05-07-07	1.0053E+003	1.0057E+003	**0.04%**	**0 - 15%**
Diesel Range C10 - C28	05-07-07	1.0270E+003	1.0274E+003	**0.04%**	**0 - 15%**

Blank Conc. (mg/L - mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	**ND**	**0.2**
Diesel Range C10 - C28	**ND**	**0.1**
Total Petroleum Hydrocarbons	**ND**	**0.2**

Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept. Range
Gasoline Range C5 - C10	**0.8**	**0.8**	**0.0%**	**0 - 30%**
Diesel Range C10 - C28	**80.1**	**79.6**	**0.6%**	**0 - 30%**

Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	Accept. Range
Gasoline Range C5 - C10	**0.8**	**250**	**250**	**99.8%**	**75 - 125%**
Diesel Range C10 - C28	**80.1**	**250**	**330**	**99.8%**	**75 - 125%**

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **QA/QC for Samples 43289 - 43291, 43302 - 43308**

Analyst

Review

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505 • 632 • 0615 • Fax 505 • 632 • 1865

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021
AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	10-10-BTEX QA/QC	Date Reported:	10-10-07
Laboratory Number:	43289	Date Sampled:	N/A
Sample Matrix:	Soil	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	10-10-07
Condition:	N/A	Analysis:	BTEX

Calibration and Detection Limits (ug/L)	I-Cal RF:	C-Cal RF:	%Diff. Accept. Range 0 - 15%	Blank Conc	Detect. Limit
Benzene	1.1750E+008	1.1774E+008	0.2%	ND	0.1
Toluene	1.0089E+008	1.0109E+008	0.2%	ND	0.1
Ethylbenzene	8.0712E+007	8.0874E+007	0.2%	ND	0.1
p,m-Xylene	1.6040E+008	1.6072E+008	0.2%	ND	0.1
o-Xylene	7.7993E+007	7.8150E+007	0.2%	ND	0.1

Duplicate Conc. (ug/Kg)	Sample	Duplicate	%Diff.	Accept Range	Detect. Limit
Benzene	1.6	1.6	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	3.1	3.1	0.0%	0 - 30%	1.0
p,m-Xylene	68.4	68.3	0.1%	0 - 30%	1.2
o-Xylene	17.8	17.7	0.6%	0 - 30%	0.9

Spike Conc. (ug/Kg)	Sample	Amount Spiked	Spiked Sample	% Recovery	Accept Range
Benzene	1.6	50.0	51.5	99.8%	39 - 150
Toluene	ND	50.0	49.9	99.8%	46 - 148
Ethylbenzene	3.1	50.0	53.0	99.8%	32 - 160
p,m-Xylene	68.4	100	168	99.8%	46 - 148
o-Xylene	17.8	50.0	67.7	99.9%	46 - 148

ND - Parameter not detected at the stated detection limit.

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.
Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments: **QA/QC for Samples 43289 - 43291, 43302 - 43306**

Analyst

Review

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505 • 632 • 0615 • Fax 505 • 632 • 1865