API# 30.039.30687

ConocoPhillips

Schematic - Current

SAN JUAN 28-7 UNIT #257N

Most Recent Job

Jobs

Job Category	Primary Job Type	Secondary Job Type	Actual Start Date	End Date
COMPLETIONS	INITIAL COMPLETION	INITIAL COMPLETION	1/14/2010	5/12/2010

Well Config: DEVIATED - Original Hole, 5/14/2010 10:33:52 AM

ftKB (MD)	Schematic - Actual
16	3-3, Casing Pup Joint, 4 1/2, 4.000, 16
	3-2, Casing Hanger, 4 1/2, 4.000, 16
17	3-1, Casing Pup Joint, 4 1/2, 4 000, 16
	2-1, Casing Hanger, 7, 6.366, 16, 1.0
19	1-1, Casing Hanger, 9 5/8, 9.001, 16, 3 3
25	2-2, Casing Pup Joint, 7, 6.366, 17, 8.0
100	
229	1-2, Casing Joints, 9 5/8, 9 001, 19, 210.1
230	1-3, Saw Tooth Collar, 9 5/8, 9.001, 229, 0.9
235	
550	
2,694	1-1, Tubing, 2 3/8, 1.995, 16, 7,976.7
4,176	2-3, Casing Joints, 7, 6.366, 25, 4,150 9
4,177	2-4, Float Collar, 7, 6 366, 4,176, 1 0
4,198	3-4, Casing Joints, 4 1/2, 4 000, 16, 4,181.4
4,207	3-5, Marker Joint, 4 1/2, 4 000, 4,197, 10.0
4,220	2-5, Casing Joints, 7, 6.366, 4,177, 42.8
4,221	2-6, Float Shoe, 7, 6.366, 4,220, 1 0
4,230	
5,172	Perforated, 5,172-5,466, 4/7/2010
5,466	
5,524	PERFORATED, 5,524-5,920, 4/7/2010
5,920	
7,709	3-6, Casing Joints, 4 1/2, 4.000, 4,207, 3,501 9
7,719	3-7, Marker Joint, 4 1/2, 4.000, 7,709, 10 0
7,892	Perforated, 7,892-8,000, 4/6/2010
7,993	1-2, Tubing Pup Joint, 2 3/8, 1.995, 7,993, 1.8
7,994	
8,000	1-3, Tubing, 2 3/8, 1 995, 7,995, 30.7
8,022	
8,025	1-4, 1.78" FN, 2 3/8, 1 780, 8,025, 0.9
8,026	1-5, 1/2 MS EXP CK., 2 3/8, 1.995, 8,026, 1.0
8,027	Perforated, 8,022-8,104, 4/6/2010
8,104	
8,108	
8,126	3-8, Casing Joints, 4 1/2, 4.000, 7,719, 406.9
8,127	3-9, Float Collar, 4 1/2, 4.000, 8,126, 0.6
8,128	3-10, Float Shoe, 4 1/2, 4.000, 8,127, 1.2
8,131	



RCVD MAY 21 '10
OIL CONS. DIV.
DIST. 3

Report Printed: 5/14/2010