

LRIC / Capataz Location

Drinkard Producer

Tested Non Commercial this Zone

N Not Deep Enough

NA Not Available

NLTI No Log this Interval

NØL No Porosity Log

LRIC / CAPATAZ OPERATING

MARSHALL # 1

Lea County, New Mexico and Gaines County, Texas

ISOPACH MAP

TOTAL DRINKARD DOLOMITE POROSITY ≥ 10%

Contour Interval = 20'

Date: May, 2001

Geology by: John Worrall

CASE NUMBER

OIL CONSERVATION DIVISION

EXHIBIT