Wellbore Diagram : NHSAU 713-30

25-34983



Tubing String Quantity (Top-Bottom Depth) Desc
1 @(15-21) J-55 2.875 OD/ 6.50# T&C External Upset 2.441 ID 2.347 Drift - Bare- - Rerun
1 @(17-3662) ESP Cable - CENTRILIFT-PART#C1030CBLYCUS AWG-4 TYPE SOLBC AROMOR GA...
1 @(3662-3962) ESP Cable - Centrilift-PART#C1030CBLYCUS-AWG-4 TYPE SOLBC AROMOR GALV...
126 @(21-4003) J-55 2.875 OD/ 6.50# T&C External Upset 2.441 ID 2.347 Drift - Bare- - Rerun
1 @(4003-4004) Seat Nipple - Heavy Duty (2.875") Cup Type- - Rerun
1 @(4004-4010) J-55 2.875 OD/ 6.50# T&C External Upset 2.441 ID 2.347 Drift - Bare- - Rerun
1 @(4010-4011) ESP Bolt on Discharge-Centrilift-Part# C63029 MODEL 400 TYPE B/O CS COATING T...
1 @(4011-4034) ESP Pump-Centrilift-PART# C323962 #STATGES 134 TYPE-FLEX17.5 MODEL400P...
1 @(4034-4058) ESP Pump-Centrilift-PART#C323962 STAGES#134STAGE-FLEX17.5MODEL-400PM...
1 @(4058-4060) ESP Gas Separator -Centrilift-PART#C323005 TYPE-GAS SEP. MODEL-400GSHVV S...
1 @(4060-4066) ESP Seal Centrilift- PART#10492077 MODEL-FSC3U PFSA CL5 FER HL PFSA STD_...
1 @(3982-4072) ESP-Motor Flat Cable PART#C78450M-110 AWG-5 TYPE KLHT ARMOR MONEL RE...
1 @(4071-4072) ESP Motor Pothead- - New
1 @(4066-4072) ESP SealCentrilift- PART#C313017048 MODELFSB3DB H6 FER SSCV SB/SB PFSA ...
1 @(4072-4086) ESP Motor-Centrilift-PART#105106829 MODEL#450SP HP110 VOLT 1550 AMP 46 C...
1 @(4086-4089) ESP Downhole Sensor Centrillift-PART#AL-13460070403 COATING 12 MIL(SS)- - New

Surface Casing (Top-Bottom Depth) Desc
@(17-1546) Cement (behind Casing) - Bare- - Good Condition
@(17-1546) J-55 8.625 OD/ 24.00# Round Short 8.097 ID 7.972 Drift - N/A- - N/A

Production Casing (Top-Bottom Depth) Desc
@(4152-4160) Perforations-Open - N/A
@(4164-4166) Perforations-Open - N/A
@(4170-4175) Perforations-Open - N/A
@(4129-4176) Perforations-Closed-Squeezed - N/A
@(4188-4191) Perforations - Open-Open - N/A
@(4188-4191) Perforations-Open - N/A
@(4214-4223) Perforations-Open - N/A
@(4227-4233) Perforations-Open - N/A
@(4234-4238) Perforations-Open - N/A
@(4242-4253) Perforations-Open - N/A
@(4264-4272) Perforations - Open-Open - N/A
@(4264-4272) Perforations-Open - N/A
@(4264-4272) Perforations - Open-Open - N/A
@(4273-4281) Perforations - Open-Open - N/A
@(4278-4283) Perforations - Open-Open - N/A
@(4292-4298) Perforations - Open-Open - N/A
@(4288-4298) Perforations - Open-Open - N/A
@(4308-4314) Perforations - Open-Open - N/A
@(4272-4314) Perforations-Open - N/A
@(4129-4314) Producing Interval-GBSA/713-30- - N/A
@(4308-4314) Perforations - Open-Open - N/A
@(17-4403) Cement (behind Casing) - Bare- - Good Condition
@(17-4403) J-55 5.500 OD/ 15.50# Round Long 4.950 ID 4.825 Drift - N/A- - N/A
@(4341-4403) Plug Back- - N/A

Wellbore Notes (Top-Bottom Depth) Desc
@(4403-4403) Total Depth- - N/A
@(4341-4403) Plug Back Total Depth- - N/A

Borehole (Top-Bottom Depth) Desc
@(17-1546) Wellbore Hole OD-12.2500 - Bare- - Good Condition
@(1546-4403) Wellbore Hole OD- 7.8750 - N/A- - N/A