District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Cross Timbers Energy, LLC	30-025-26512
Property Name	**Well No.**
Southeast Maljamar GA/SA Unit	105

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
J	30	17S	33E		2490	FSL	1595	FEL	LEA

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES (NO)	YES (NO)	(INJ) SWD	OIL GAS	3-12-20

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	-0-	n/a	n/a	-0-	-0-
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2 ____
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS ____
Down to nothing	(Y) / N	Y / N	Y / N	(N) / N	If applicable type
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	fluid injected for
Water	Y / (N)	Y / N	Y / N	Y / (N)	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Post Workover

Start - 580#
End - 575#
Cal Date - 11/7/19
Ser# 11216
Gandy #4 1000# 32 min

HOBBS OCD
JUN 03 2020
RECEIVED

Signature:		OIL CONSERVATION DIVISION
Printed name: Kevin Bennett		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 3/12/20	Phone:	
	Witness:	


MIDNIGHT
NOON
6 PM
6 AM
Graphic Controls
DATE 3-12-20
BR 2221
PRINTED IN U.S.A.