

From: [Kimberly M. Wilson](#)
To: [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)
Cc: [Christopher Jones@oxy.com](#); [David Adkins](#)
Subject: Piglet 21 CTB * 30-15-39371 * DOR 5-16-2014
Date: Thursday, September 18, 2014 12:33:47 PM
Attachments: image001.png
20140918115511709.pdf
20140918120357968.pdf

Mike and Heather,

I performed an OCD online research for the 2RP number but couldn't find where the initial C-141 had been processed. Please find attached the initial and final C-141 along with the site map and lab results. The soil testing results are under the Recommended Remedial Action Levels (RRAL's) Therefore, we respectfully ask, that no further remedial actions be required for this incident.

Thank you.

Respectfully submitted,

Kimberly M. Wilson

Project Manager

Talon/LPE

408 West Texas Avenue

Artesia, New Mexico 88210

Office: 575.746.8768

Fax: 575.746.8905

Cell: 575.602.3826

Emergency: 866.742.0742

Email: kwilson@talonlpe.com

Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist

Staples Foundation for Learning Hall of Fame Recipient:2010

ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006

Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007