

**From:** Patterson, Heather, EMNRD  
**To:** ["Kyle Norman"; djglass@blm.gov](#); ["Tucker, Shelly"; Bratcher, Mike, EMNRD](#)  
**Cc:** ["Baker, Larry"; "Lara Weinheimer"; "Amos, James"](#)  
**Subject:** RE: Apache Crow Fed #35 (2RP-2677) request to backfill above injection line  
**Date:** Wednesday, August 12, 2015 12:06:00 PM

---

**RE: Apache \* Crow Fed #35H \* 30-015-42140 \* 2RP-2677**

Kyle,

This backfill request is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Kyle Norman [mailto:knorman@basinenv.com]  
**Sent:** Monday, August 10, 2015 4:53 PM  
**To:** djglass@blm.gov; 'Tucker, Shelly'; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** 'Baker, Larry'; 'Lara Weinheimer'; 'Amos, James'  
**Subject:** Apache Crow Fed #35 (2RP-2677) request to backfill above injection line

All,

Apache is requesting to backfill above injection line on the Crow Fed #35 (2RP-2677). Linn has had the injection line shut in for 3 weeks, we would like to backfill above the line. Let me know if you have any questions.