



WPCO, L.P.
SAFETY INSTRUCTIONS
68770

CAUTION
H₂S
POISONOUS GAS

DANGER
DO NOT ENTER





Fenton 7 Federal #1

12/10/15

EHS

A. Galt

API 3D-015-27973

Unit returned to operation yesterday afternoon ~ 2 pm.
 Dump valves were replaced before return to operation.
 Multiple BOPED employees confirmed that the system
 was operating properly & fluid was dumping into tanks.
 Pumpers arrived to find fluid spilling from the flare
 stack. He checked the system & noted that the
 dump valves were closed. He opened the valves &
 notified EHS. ~ 7 am

Use truck recovered 20 bbls oil

Leak affected 840 ft² of pasture & 2064 ft² of well pad
 7 bbls PW, 5 bbls oil in soil

GPS 32.496615° N
 -104.132350° W

