

## **Bratcher, Mike, EMNRD**

---

**From:** Chase Settle <CSettle@yatespetroleum.com>  
**Sent:** Thursday, March 13, 2014 4:57 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** jamos@blm.gov; Duncan Whitlock (dwhitloc@blm.gov); Bob Asher  
**Subject:** C141 Grateful BOD Federal Com. #1-H FINAL  
**Attachments:** C141 Grateful BOD Federal Com. #1-H FINAL.pdf

RE: Grateful BOD Federal Com. #1-H

30-015-38990

Section 13, T18S-R29E

Eddy County, NM

Mr. Bratcher,

Enclosed please find a Form C-141, Final Report for the above captioned site regarding the release on 02/19/2014 (15 bbls of oil with 10 bbls of oil recovered). The cause of the release was due to pumping unit going down and oil being forced through the e-pot releasing oil onto the production pad. The release area was sampled on 03/04/2014 and sent for analysis (TPH and BTEX) at an NMOCD approved laboratory. The results for BTEX and Total TPH are below the RRAL's for the site ranking of 0 and depth to groundwater is approximately 175' per the ChevronTexaco Trend Map. Based on the enclosed analytical sampling results and depth to groundwater, Yates Petroleum Corporation requests closure. The affected soils were excavated and taken to an approved NMOCD facility.

If you have any questions, please call me at 575-748-4171.

Thank you,

**Chase Settle**  
**Environmental Regulatory Agent**  
**Yates Petroleum Corporation**  
**105 S. 4<sup>th</sup> Street**  
**Artesia, NM 88210**  
**575-748-4171 (Office)**  
**575-703-6537 (Cell)**

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

