From:	Weaver, Crystal, EMNRD
To:	<u>"Blaney, Karolina"</u>
Cc:	Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject:	RE: WPX RDX 15-11 - fire and spill notification
Date:	Friday, December 16, 2016 10:08:00 AM
Attachments:	1.COA for 2RP-4032.pdf

RE: WPX Energy/RKI 8 RDX 15-11 \* 30-015-37093 \* 2RP-4032

Karolina,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4032.

Thank you,

## **Crystal Weaver**

Environmental Specialist OCD – Artesia District II 811 S. 1<sup>st</sup> Street Aretesia, NM 88210 Office: 575-748-1283 Fax: 575-748-9720

From: Patterson, Heather, EMNRD
Sent: Monday, December 5, 2016 11:05 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: FW: WPX RDX 15-11 - fire and spill notification

printed

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Monday, December 05, 2016 11:03 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'
Subject: WPX RDX 15-11 - fire and spill notification

Good afternoon,

On 12/4/16, WPX had a small fire on the RDX 15-11 well pad; API # 30-015-37093 located in qtr/qtr F, Section 15, T26S R30E. The fire did not spread beyond the SPCC containment berm and was most likely caused by malfunction of the heater treater. As a result, estimated 120 bbls of water and small amount of oil (approximately 1 bbls) got spilled. The majority of the spill was contained inside dirt SPCC berm. Approximately 1-2 bbls sprayed outside the containment. The C-141 report will be submitted within 15 days from the incident. Please let me know if you have any questions or concerns. Thank you and have a great day,

## Karolina Blaney

Environmental Specialist WPX Energy Cell: (970) 589-0743 karolina.blaney@wpxenergy.com