

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

2RP-1929 and 2RP-1917

nJMW1326331941 2RP-1917

fJMW1326331184

nJMW1326734243 2RP-1929

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	<i>Enterprise Field Services LLC</i>	Contact	<i>Alena Miro</i>
	<i>PO Box 4324, Houston, TX 77252</i>	Telephone No.	<i>575-628-6802</i>
Facility Name	<i>Pipeline ROW, Mercury Fee Line</i>	Facility Type:	<i>Gas Gathering Pipeline</i>
Surface Owner	<i>Private-McDonald</i>	Mineral Owner	<i>NA</i>
		Lease No.	<i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>18</i>	<i>23S</i>	<i>28E</i>					<i>Eddy</i>

Latitude *32.29873 N* Longitude *-104.11864 W*

NATURE OF RELEASE

Type of Release	<i>Natural Gas and Pipeline Liquids</i>	Volume of Release	<i>248 MCF gas and 108 BBL pipeline liquids</i>	Volume Recovered	<i>NA</i>
Source of Release	<i>Pipeline Leak</i>	Date and Hour of Occurrence	<i>09/06/2013 06:45 (MDT)</i>	Date and Hour of Discovery	<i>09/06/2013 07:30 (MDT) finish</i>
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<i>Mike Bratcher, NMODC Region 2</i>		
By Whom?	<i>Jim Heup</i>	Date and Hour	<i>10/13/2013 @ 09:36 MDT</i>		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Suspected internal corrosion. The line was isolated, blown-down and repaired. Maintenance excavation on 12SEP2013 found a release of pipeline liquids.

Describe Area Affected and Cleanup Action Taken.*

Impacted soils have been delineated and sent to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	<i>Jon E. Fields</i>		
Title:	<i>Director - Field Environmental</i>		
E-mail Address:	<i>snolan@eprod.com</i>		
Date:	<i>12/20/2016</i>		
Phone:	<i>713-318-6595</i>		
OIL CONSERVATION DIVISION		Approved by District Supervisor: 	
Approval Date: <i>4/28/17</i>		Expiration Date: <i>N/A</i>	
Conditions of Approval: <i>N/A</i>		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1917 & 2RP-1929