From:
 Weaver, Crystal, EMNRD

 To:
 "Potter, Dennis"

 Cc:
 Bratcher, Mike, EMNRD

 Subject:
 RE: WB#30 spill report 9-2-17

**Date:** Monday, September 25, 2017 12:44:00 PM

## Dennis,

I got your voicemail. I am not sure what there is to discuss regarding the distance between the two releases or the time from which they both come from. It appears according to your labeling on the GE image you attached that they are relatively close to one another. If 2RP-2462 has not already been previously remediated then is would be ideal if both of these releases could be taken care of all at once. Please advise OCD on the status of the older release (2RP-2462) and what Linn Energy's intentions are to resolve that release and the current release (2RP-4375).

Thank you,

## **Crystal Weaver**

Environmental Specialist OCD – Artesia District II 811 S. 1<sup>st</sup> Street Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963 Fax: 575-748-9720

**From:** Potter, Dennis [mailto:DPotter@linnenergy.com]

Sent: Monday, September 25, 2017 11:13 AM

**To:** Weaver, Crystal, EMNRD < Crystal. Weaver@state.nm.us>

Subject: RE: WB#30 spill report 9-2-17

## Crystal,

I have attached a google earth shot of the 2 injection leaks in question. I dropped a pin on both sites and dated them. I will call you so we can talk about this.

Thanks Dennis

**From:** Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]

Sent: Friday, September 22, 2017 3:41 PM

**To:** Potter, Dennis < <u>DPotter@linnenergy.com</u>>; Bratcher, Mike, EMNRD

<mike.bratcher@state.nm.us>; Tucker, Shelly <stucker@blm.gov>

**Subject:** RE: WB#30 spill report 9-2-17

RE: Linn Energy \* H.E. West B #30 \* 30-015-10705 \* 2RP-4375

Dennis,

Sorry for the delay on sending this one out. I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4375. Please remit a site characterization plan or advise OCD of plan of action by no later than 10/5/17.

Please note: I was looking in the records for this location and I found an old case numbered 2RP-2462 that according to our records nothing else has been sent in since the initial C-141. Please provide an update for this release.

Thank you,

## **Crystal Weaver**

Environmental Specialist OCD – Artesia District II 811 S. 1<sup>st</sup> Street Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963 Fax: 575-748-9720

----Original Message-----

From: Potter, Dennis [mailto:DPotter@linnenergy.com]

Sent: Tuesday, September 5, 2017 11:13 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD

<<u>Crystal.Weaver@state.nm.us</u>>; Tucker, Shelly <<u>stucker@blm.gov</u>>

Subject: WB#30 spill report 9-2-17

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this

message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return email and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.