Bratcher, Mike, EMNRD

From: Heather Patterson < heather.patterson@soudermiller.com>

Sent: Monday, November 13, 2017 3:31 PM

To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; 'Amber Groves'

Cc:Austin Weyant; james campanellaSubject:Ford State #2 2RP-4390 backfill requestAttachments:table 3.pdf; Ford State #2 fig 2.pdf

Good Afternoon,

After hydro-excavating this location, we still returned some elevated chlorides. Due to the proximity to pipelines and the hard-pan rock layer, further remediation is not practicable. At this time we would like to request backfill so we can then establish a healthy vegetative layer to aid in the stabilization of the remaining contaminants.

Thank you,

Heather Patterson Staff Scientist

Souder, Miller & Associates

Engineering ♦ Environmental ♦ Surveying 201 Halagueno St Carlsbad, NM 88220 www.soudermiller.com (575)200-5343 (mobile)

