

From: Tucker, Shelly
To: [Debeyessey, Svetlana](#)
Cc: [DeLeon, Josepha](#); [Weaver, Crystal, EMNRD](#); [Bratcher, Mike, EMNRD](#); [Meaux, Luke](#); [Leonard, Nicklois L](#)
Subject: Re: Re: Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud
Date: Thursday, March 15, 2018 4:13:42 PM

Was checking on the status of this release.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Dec 26, 2017 at 10:35 AM, Debeyessey, Svetlana <LDebeyessey@chevron.com> wrote:

Shelly,

The rig has recently been moved and we were able to schedule delineation sampling and development of the remediation plan. If the weather permits the crew will take delineation samples this week. Once the plan is prepared it will be submitted to Crystal Weaver and yourself at the earliest possible date. Please let us know if there are any concerns.

Happy Holidays!

Lana Debeysey

Field HES Compliance Supervisor

MCBU Midland

O: 432-687-7234

M: 432-258-9584

E-Mail: LDebeysey@chevron.com

[Your CSOC feedback would be appreciated. This feedback will help me have a better understanding of my leadership and CSOC behaviours strengths and improvement opportunities.](#)

From: Tucker, Shelly [mailto:stucker@blm.gov]

Sent: Thursday, December 21, 2017 4:48 PM

To: DeLeon, Josepha <JDXD@chevron.com>

Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Debeysey, Svetlana <LDebeysey@chevron.com>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>

Subject: [**EXTERNAL**] Re: Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

Wanted to get an update on the status of this release.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

[575.234.5905](#) - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Oct 3, 2017 at 10:27 AM, DeLeon, Josepha <JDxD@chevron.com> wrote:

| Shelly / Crystal, I spoke to Mike and explained that the drilling rig is still at this site.

As soon as drilling is completed and the rig is moved off remediation will begin according to conditions of approval.

Thank you for your follow up.

From: Tucker, Shelly [mailto:stucker@blm.gov]
Sent: Thursday, September 28, 2017 9:56 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: DeLeon, Josepha <JDXD@chevron.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Debeysey, Svetlana <LDebeysey@chevron.com>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>
Subject: [**EXTERNAL**] Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

What is the status of this release?

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

[575.234.5905](tel:575.234.5905) - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Sat, Jul 8, 2017 at 2:51 PM, Tucker, Shelly <stucker@blm.gov> wrote:

Thank you for the C-141.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

[575.234.5905](#) - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Wed, May 17, 2017 at 5:00 PM, Weaver, Crystal, EMNRD
<Crystal.Weaver@state.nm.us> wrote:

Josie,

There were some issues trying to be sure what locational information that was on the C-141 was correct, however, it seems that the coordinates are right cause they match the API location so Olivia forwarded this one on to District II OCD Office. I was not sure if Shelly Tucker had originally been copied on this one or not so I included her. Also we did get an immediate notification from you on this one to District II. So I am thinking the Initial C-141 just made it to Olivia and Co. in District 1 as a miss shuffle. Either way no biggie just wanted to make sure it is now where it is supposed to be.

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4202.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

[811 S. 1st](#) Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Yu, Olivia, EMNRD

Sent: Wednesday, May 3, 2017 1:44 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: FW: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

From: DeLeon, Josepha [<mailto:JDxD@chevron.com>]
Sent: Monday, May 1, 2017 9:24 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Brown, Maxey G, EMNRD <MaxeyG.Brown@state.nm.us>
Cc: Debeysey, Svetlana <LDebeysey@chevron.com>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>
Subject: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

Attached is the C-141 for the spill that occurred at Hayhurst SO 10 P3 24 H.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(New Mexico, East Texas and Ft. Stockton Areas)

[1616 W. Bender Blvd.](#)

[Hobbs, NM 88240](#)

[575-263-0424](#)

432-425-1528 - cell

jdxd@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker

