

**From:** [Weaver, Crystal, EMNRD](#)  
**To:** ["Jennifer Knowlton"; Naranjo, Mark](#)  
**Cc:** [Sheldon Hitchcock](#); [Rebecca Haskell](#); [Dakota Neel](#); [Maurice Foye](#); [Honea, Tammy](#); [Mann, Ryan](#)  
**Subject:** RE: Concho SRO State Com #13H Work Plan \* 30-015-37427 \* 2RP-4313  
**Date:** Tuesday, April 24, 2018 3:42:00 PM

---

RE: COG \* SRO State COM #13H \* 30-015-37427 \* 2RP-4313 and 2RP-4328

Hello all,

Jennifer thank you for the submission of this work plan, however, OCD would like to start with saying it may be best that yourself, and any other participating members of HRL Compliance Solutions that contributed to this work plan, get with COG members, mentioned above, on what they are aware of that OCD expects within a work plan.

- An outline showing the parameters for each spill impact of 2RP-4313 and 2RP-4328 would be helpful unless both spills are in fact an exact overlap.
- One sample point within the area of the spill is not adequate representation of portraying the impact accumulation especially based on a site where COG indicates a net loss of 24bbbls occurred.
- Sample testing is inadequate. You must start testing for all required constituents mentioned in OCD's COA document at each sample point till they show clean or at least check at more than just the one sample point on all constituents.
- Also the first release involved what was stated as a lightning strike which hit a tank and caused tank overflow. What has been done regarding resolution of the tank battery area? Would not some of the release impact the fill material that is within the lined battery area? Was the liner inspected to verify it held its integrity? Was the liner impacted by the lightning strike? Please address these matters.

Also for this site I show it having a lower elevation (3032 ft elev.) than a well that is documented by USGS as 320230104060601 (3048 ft. elev.) that has a depth to ground water of 17.52ft and is almost as equally far away on the west side from the spill site location as a number of the wells that OSE documents as showing depth to water on the east side of spill site location at around the 120ft depth (OSE well number C-2160 etc.). Also the area that the well pad is in proximity to what appears to be a drainage feature that has not only what appears to be an association to an ephemeral playa but also feeds as a water drainage source to the Delaware River which runs east to west and is directly south of the well site location.

- Thus likelihood of encountering shallow ground water for this location is high. Therefore, OCD will have to override the site ranking and give this site a site ranking of at least a 10, therefore changing target action clean up levels.

**This work plan as written is denied. Please provide a new work plan with proper delineation efforts and representative sampling data and which also addresses any and all other matters OCD has mentioned.**

Thank you,

## Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720



---

**From:** Jennifer Knowlton <jknowlton@hrlcomp.com>  
**Sent:** Monday, March 26, 2018 12:58 PM  
**To:** Naranjo, Mark <MNaranjo@slo.state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>  
**Cc:** Sheldon Hitchcock <SLHitchcock@concho.com>; Rebecca Haskell <RHaskell@concho.com>; Dakota Neel <DNeel2@concho.com>; Maurice Foye <mfoye@hrlcomp.com>; Honea, Tammy <thonea@slo.state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>  
**Subject:** RE: Concho SRO State Com #13H Work Plan \* 30-015-37427 \* 2RP-4313

Mr. Naranjo:

I have attached a revised work plan that includes a revegetation plan.

**Jennifer Knowlton, PE** | Regional Manager Permian Basin  
HRL Compliance Solutions, Inc.

main 970.243.3271 | mobile 505-238-3588  
[Web](#) | [vCard](#) | [Map](#) |  | 

HRL Logo



Confidentiality Note: This email and any attachments are confidential and only for the use as authorized by HRL Compliance Solutions, Inc. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information. Permanently delete the e-mail and any attachments or copies.

---

**From:** Naranjo, Mark [mailto:MNaranjo@slo.state.nm.us]

**Sent:** Tuesday, March 20, 2018 8:34 AM

**To:** Jennifer Knowlton <jknowlton@hrlcomp.com>; Crystal.Weaver@state.nm.us

**Cc:** Sheldon Hitchcock <SLHitchcock@concho.com>; Rebecca Haskell <RHaskell@concho.com>; Dakota Neel <DNeel2@concho.com>; Maurice Foye <mfoye@hrlcomp.com>; Honea, Tammy <thonea@slo.state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>

**Subject:** RE: Concho SRO State Com #13H Work Plan \* 30-015-37427 \* 2RP-4313

The NMSLO approves this work plan pending any other requirements from NMOCD. Please submit a revelation plan to the NMSLO at your earliest convenience.

Mark Naranjo  
Assistant Division Director  
Field Operations Division  
575.623.4979 Office  
575.626.2678 Cell  
575.623.9200 Fax  
New Mexico State Land Office  
1001 S. Atkinson  
Roswell, NM 88203  
[MNaranjo@slo.state.nm.us](mailto:MNaranjo@slo.state.nm.us)  
[NMStatelands.org](http://NMStatelands.org)

.....  
CONFIDENTIALITY NOTICE: This e-mail, including all attachments is for the sole use of the intended recipient[s] and may contain confidential and/or privileged information. Any unauthorized review, use, copying, disclosure or distribution is prohibited, unless specifically provided under the New Mexico Inspection of Public Records Act. If you are not the intended recipient, please contact the sender at once and destroy all copies of this message

---

**From:** Jennifer Knowlton [<mailto:jknowlton@hrlcomp.com>]

**Sent:** Monday, March 19, 2018 2:03 PM

**To:** [Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us); Naranjo, Mark <[MNaranjo@slo.state.nm.us](mailto:MNaranjo@slo.state.nm.us)>

**Cc:** Sheldon Hitchcock <[SLHitchcock@concho.com](mailto:SLHitchcock@concho.com)>; Rebecca Haskell <[RHaskell@concho.com](mailto:RHaskell@concho.com)>; Dakota Neel <[DNeel2@concho.com](mailto:DNeel2@concho.com)>; Maurice Foye <[mfoye@hrlcomp.com](mailto:mfoye@hrlcomp.com)>

**Subject:** Concho SRO State Com #13H Work Plan \* 30-015-37427 \* 2RP-4313

Ms. Weaver/Mr. Naranjo,

On behalf of COG Operating, I have attached a work plan for the SRO State Com #13H for your consideration. Please feel free to contact me if you have any questions or concerns.

Thank you,

**Jennifer Knowlton, PE** | Regional Manager Permian Basin  
HRL Compliance Solutions, Inc.

main 970.243.3271 | mobile 505-238-3588

[Web](#) | [vCard](#) | [Map](#) |  | 

HRL Logo



Confidentiality Note: This email and any attachments are confidential and only for the use as authorized by HRL Compliance Solutions, Inc. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information. Permanently delete the e-mail and any attachments or copies.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---