

From: [Randall Hicks](#)
To: ["Glass, Dara"; Patterson, Heather, EMNRD](#)
Cc: ["Larry"](#)
Subject: Marker Oil - NSLU releases
Date: Monday, April 18, 2016 11:27:07 AM
Attachments: image001.png

Ms. Glass and Ms. Patterson

Last week, Mr. Marker and I examined the sites listed below. However, we looked at the wrong #39 site as we were examining a historic release site, not the one noted below.

I thought that the work done by eTech was good as were most of the CAPs – all of which have been approved. Our recommendation is this:

1. Create a schedule of implementation of the corrective actions based upon a prioritization and submit to BLM and OCD. At this time, we anticipate implementing at least 3 of the remedies every two months. We would like to take advantage of any monsoon while at the same time considering the price of oil and time allocation for the small staff of Marker Oil.
2. We intend to present some minor modifications to the approved CAPs. Initially, we do not see much benefit to the addition of imported fresh water or the fertilizer to this very sandy soil. We ask for a week to come up with some different ideas or to keep the CAPs "as is".

Please expect the schedule of work by next Monday with implementation of the first remedy within 3 weeks from today. Also next Monday you will receive the first CAP under Marker Oil for these sites.

If your files show different sites than these, please let us know so we can all work off the same page.

Thanks!

Grier Battery	7/24/2015	32.879858, -103.911067	NA	
NSLU #3	8/6/2015	32.904763, -103.898751	2RP-3243	
NSLU Inj Line #51 & #69	9/13/2015	32.8889, -103.923224	2RP-3261	
NSLU #100	9/24/2015	32.885231, -103.909161	2RP-3281	
NSLU #3 Inj Line	10/12/2015	32.903056, -103.896083	2RP-3333	
Federal R6	10/28/2015	32.8554, -103.952752	2RP-3363	
Loco Hills A6	10/25/2015	32.839367, -103.965968	2RP-3355	
NSLU 197	10/29/2015	32.903050, -103.899767	2RP-3381	
NSLU 100 Injection Line	12/2/2015	32.882011, -103.908675	2RP-3448	
NSLU #39		32.897127, -103.902969		
NSLU #3 Inj Line 3rd Release	12/5/2015	32.904084, -103.895592	2RP-3447	

Randall Hicks
 R.T. Hicks Consultants
 Cell: 505-238-9515
 Office: 505-266-5004