

**From:** [Pruett, Maria, EMNRD](#)  
**To:** ["DeAnn Grant"; Tucker, Shelly](#)  
**Cc:** [Bratcher, Mike, EMNRD](#); [Griswold, Jim, EMNRD](#); [jamos@blm.gov](#); [Ike Tavarez](#); [Robert McNeill](#); [Sheldon Hitchcock](#); [Dakota Neel](#); [Rebecca Haskell](#)  
**Subject:** 2RP-5055 RE: (C-141 Initial) Hobgoblin 7 Federal Com UBB #004H (30-015-41815) 11-03-2018  
**Date:** Wednesday, November 21, 2018 11:11:00 AM  
**Attachments:** [image001.png](#)

---

Hello Ms. Grant,

OCD has received the C-141 Release Notification, thank you! It has been assigned 5055. Please let me know if you have any questions.

Best Regards,

*Maria Pruett*

Environmental Specialist  
N.M. Oil Conservation Division  
District 2  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Desk: 575 748-1283 X 101  
Cell: 575 840-5963  
Fax: 575748-9720

---

**From:** DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Sent:** Friday, November 16, 2018 8:44 AM  
**To:** Pruett, Maria, EMNRD <[Maria.Pruett@state.nm.us](mailto:Maria.Pruett@state.nm.us)>; Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Griswold, Jim, EMNRD <[Jim.Griswold@state.nm.us](mailto:Jim.Griswold@state.nm.us)>; [jamos@blm.gov](mailto:jamos@blm.gov); [Ike Tavarez <itavarez@concho.com>](mailto:itavarez@concho.com); [Robert McNeill <RMcNeill@concho.com>](mailto:RMcNeill@concho.com); [Sheldon Hitchcock <SLHitchcock@concho.com>](mailto:SLHitchcock@concho.com); [Dakota Neel <DNeel2@concho.com>](mailto:DNeel2@concho.com); [Rebecca Haskell <RHaskell@concho.com>](mailto:RHaskell@concho.com); DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Subject:** [EXT] (C-141 Initial) Hobgoblin 7 Federal Com UBB #004H (30-015-41815) 11-03-2018

Ms. Pruett/Ms. Tucker,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume for Falcon Lined facilities. The liquid lost estimate is based on the spill dimensions and estimated depth of fluid in the liner. The spreadsheet will calculate the volume lost into the liner. No gravel was present in this lined facility as it is a Falcon Liner. The unrecovered volume is a residue left behind on the liner and equipment which will be cleaned by pressure wash. If you have any questions or concerns please do not hesitate to contact me

Thank you,

*DeAnn Grant*

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.