

From: [Pruett, Maria, EMNRD](#)
To: ["Karrigan, Callie N. \(MRO\)"; Griswold, Jim, EMNRD; Bratcher, Mike, EMNRD; Mann, Ryan](#)
Cc: [Heather Patterson; Castro, Isaac \(MRO\)](#)
Subject: 2RP-5064 RE: Marathon Oil Company - Initial C141 - Black River 15 10 State Com X 4H
Date: Sunday, November 25, 2018 11:54:00 AM

Hello Ms. Karrigan,

OCD has received the C-141 Release Notification, thank you! It has been assigned 2RP-5064.

Best Regards,

Maria Pruett

Environmental Specialist
N.M. Oil Conservation Division
District 2
811 S. 1st Street
Artesia, NM 88210
Desk: 575 748-1283 X 101
Cell: 575 840-5963
Fax: 575748-9720

From: Karrigan, Callie N. (MRO) <cnkarrigan@marathonoil.com>
Sent: Monday, November 19, 2018 10:34 AM
To: Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Heather Patterson <heather.patterson@soudermiller.com>; Castro, Isaac (MRO) <icastro@marathonoil.com>
Subject: [EXT] Marathon Oil Company - Initial C141 - Black River 15 10 State Com X 4H

Good morning,

Please see the attached initial C141.

Thank you and Happy Thanksgiving!

Callie

From: Karrigan, Callie N. (MRO)
Sent: Monday, November 5, 2018 5:57 PM
To: 'Pruett, Maria, EMNRD' <Maria.Pruett@state.nm.us>; 'jim.griswold@state.nm.us' <jim.griswold@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: 'Heather Patterson' <heather.patterson@soudermiller.com>; Castro, Isaac (MRO)

<icastro@marathonoil.com>

Subject: Marathon Oil Company - 24 hour notice - Black River 15 10 State Com X 4H

Good evening,

At approximately 2:30 am, a 3rd party hauler reported an overspray from the facility. Upon immediate inspection by the Field Operator, it was found that the high pressure separator manway gasket failed. Approximately 149 barrels of produced water was released. 23 barrels of the release traveled off location and affected a 0.23 acre area. Standing fluids were immediately recovered. The well has been shut-in pending manway gasket repair on the vessel. A C141 will be submitted shortly.

We also had Surveyors onsite to survey the affected area offsite. I will share that as soon as it is received.

API – 30-015-43959

Thank you,

Callie Karrigan

HES Professional – Environmental

Office: 575-297-0956

Cell: 405-202-1028