

Bratcher, Mike, EMNRD

From: Mann, Ryan <rmann@slo.state.nm.us>
Sent: Thursday, January 17, 2019 4:43 PM
To: 'Cooper, Brian'; Bratcher, Mike, EMNRD
Cc: itavarez@concho.com; rhaskell@concho.com; DeAnn Grant; Stoffel, Jared
Subject: [EXT] RE: 2RP-4645 - Site Assessment Summary and Deferral Request - Graham Cracker 16 State # 002H

Good afternoon,

NMSLO denies the risk based closure request. The closest well I could find was in the USGS database, and was located about 4200' to the SW and has a depth of 16 feet the last time it was measured. Because of this information the site required further delineation. Also the TPH seems high to me for a produced water release. The site need to be delineated to 600ppm chloride, 100ppm TPH, 50 BTEX, and 10ppm Benzene. Finally, my inclination, even without seeing full delineation data would be to deny deferral. Deferral is for production equipment and facilities. This looks be to located in an area where remediation is feasible.

Let me know if you have any questions.

Ryan Mann
Remediation Specialist
Field Operation Division
(575) 392-3697
(505) 699-1989
New Mexico State Land Office
2827 N. Dal Paso Suite 117
Hobbs, NM 88240



From: Cooper, Brian [mailto:BCooper@trcsolutions.com]
Sent: Thursday, January 3, 2019 9:50 AM
To: mike.bratcher@state.nm.us; Mann, Ryan <rmann@slo.state.nm.us>
Cc: itavarez@concho.com; rhaskell@concho.com; DeAnn Grant <agrants@concho.com>; Stoffel, Jared <JStoffel@trcsolutions.com>
Subject: 2RP-4645 - Site Assessment Summary and Deferral Request - Graham Cracker 16 State #002H

Mr. Bratcher and Mr. Mann,

Please find attached the *Site Assessment Summary and Deferral Request* that has been prepared for the COG Operating, LLC Release Site known as the Graham Cracker 16 State #002H. The site is located in UL "N", Section 9, Township 26 South, Range 28 East, in Eddy County, New Mexico. If you have any questions or need any additional information, please feel free to contact Becky Haskell, Ike Tavarez, or myself.

Respectfully,

Brian Cooper
Enviromental Tech III



2771 State Highway 214, Denver City, TX 79323
| C: 806 401 5356

[LinkedIn](#) | [Twitter](#) | [Blog](#) | www.trcsolutions.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit https://clicktime.symantec.com/a/1/GbvTsurG0XvZJrgwKV9WNR-5FptzSnHBzfFxI2mK0KI=?d=FxVFDDK6n9qY2SkG8vcVcv-8sSuN0r1G6Ds6E1Zvg80cuhX2D6zZ0AVrIXOH_7s1d3rcBBQJv0dKkZoRgmhWs0qUyNTQb8qkcPggxoiokfwmpRJxYgPBgDF0ltVKg6W0m3LlrtGMjv_m2oj_F_hof7chnpWgw7T5wqUqhhDPLndXwxE26pVh72ZLnI3P5sbYd7Aj2tJYySQykdhUrNBwY9IMLLn4on6_XxJbsQfHwXvS-vI3VIMXTRKNNyQYdoOPY1N5zoY23vgJqgb9NDe4H0aUNPa7V4X2JGReEN73_QMsTBUTm3gBZvt7zS29Pf3zLxcSkSj3fZl4nU1I5o5Ix-FGqQJmUW1257Pp7JJxQ4CVoyYFKioZaR3GwbLrGH3Qt5etL1ehFjjuul2aSQeBQgdfYIHqjz9VKw0jHS4XnG7m91uO1EeHnLyIDVtYWvAZh68Qf8lFng%3D%3D&u=http%3A%2F%2Fwww.symanteccloud.com
