Hamlet, Robert, EMNRD

From: Melodie Sanjari <melodie.sanjari@soudermiller.com>

Sent: Wednesday, February 20, 2019 2:20 PM

To: Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Bratcher, Mike, EMNRD

Cc: John Hurt; Austin Weyant

Subject: [EXT] Janie Conner Tank Battery 24 Hour Notification

Responsible Party:

Matador Resources Company

OGRID: 228937

5400 LBJ Freeway, Suite 1500 Dallas, TX 75240

John Hurt

JHurt@matadorresources.com

972-371-5200

Location:

MATADOR PRODUCTION COMPANY

Janie Conner Tank Battery UL:A S: 14 T24S R28E API: 30-015-43463

Facility Type: Tank Battery

GPS Location: 32.2219634 -104.0504256

Surface Land Owner:

Cause of Release: Equipment Failure – Fire Tube on Heater Treater

Release Material: Produced Water & Crude Oil

Pathway: The release occurred around heater treated and flowed west to the battery containment and travelled south

off the pad into a San Mateo pipeline ROW

Initial Action: Source was eliminated and surficial material was recovered

Date of Discovery: 2/19/2019

Estimated surface release area: 300 square yards

Estimated Volume loss: Predicted to be less than 25 bbls

Estimated Volume Recovered: vac truck responded; approx. 10 bbls

Melodie Sanjari

Staff Scientist



Souder, Miller & Associates

Engineering ♦ Environmental ♦ Surveying 201 S Halagueno Street Carlsbad, NM 88220 www.soudermiller.com (574) 370-9782 (cell) (505) 299-0942 Ext. 2204



Notice of Confidentiality and Privileged Status: This electronic mail message, including all attachments, is for the sole use of the intended recipient(s) and may contain confidential and/or privileged information or otherwise may be protected from disclosure. Any unauthorized review, use, disclosure, distribution or actions which rely on the contents of this information is prohibited. If you are not the intended recipient, please contact the sender and delete the message and any attachment(s) from your system.

Statement on Viruses and Harmful Software: While the message and attachment(s) have been scanned with anti-virus software, SMA does not guarantee that this message or any attachment(s) is free of computer viruses or other harmful software. SMA does not accept liability for any damages caused by any computer virus or other harmful software transmitted herewith.