

Inspector :	Dave Nunley
Date & Time:	10/18/20
RWCS Name:	HHNM 2 East

NMOCD Registration number:	2RF-120
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	NOTE: The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	NOTE: Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	NOTE: If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading			
<p>NOTE:</p> <p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<p>The pond currently has Brackish water/ TKT DS20396503</p>			