

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

0454018

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED BY  SEP 21 1983  O. C. D. DISTRICT OFFICE	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Union Oil Company of California			8. FARM OR LEASE NAME Wersell Federal	
3. ADDRESS OF OPERATOR P. O. Box 671 Midland, Texas 79702			9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 810' FNL & 1980' FWL Sec 4, T-22-S R-27-E			10. FIELD AND POOL, OR WILDCAT Undesignated (Delaware)	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,152' GR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 4, T-22-S R-27-E		12. COUNTY OR PARISH Eddy County
		13. STATE New Mexico		

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Plug Back to Delaware - Oil</u>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 8-10-82 - MI RU, cut 2-3/8" OD tbg @ 11,097' and pull tbg.
- 8-12-82 - Set CIBP on wireline @ 11,090. Plug No. 1 - spot cmt plug 11,090' - 11,044'.
- 8-15-82 - Shot and pulled 5-1/2" OD csg @ 6,971' - pulled 223 jts.
- 8-19-82 - Ran 2-3/8" OD tbg to 7,060'. Plug No. 2 - spot 50 sx cmt 7,060' - 6,860'. Pull tbg to 5,334'. Plug No. 3 - spot 50 sx cmt 5,334' - 5,184'.
- 8-25-82 - Perf Delaware thru 9-5/8" OD csg 4,458'-66'. Acidized perfs w/1500 gals 7-1/2% HCL acid.
- 8-31-82 - Perf Delaware sand 4,392'-96' and acidized w/600 gals 7-1/2% HCL acid.
- 9- 2-82 - Perf Delaware sand 4,298'-4,314' and acidized w/500 gals 7-1/2% HCL acid.
- 9-10-82 - Sqzd Delaware perfs 4,298'-4,314' w/75 sx Class "C" cmt.
- 9-22-82 - Set pkr @ 4,334', sand-water frac Delaware perfs 4,392'-96' - 4,458'-4,466' w/15,375 gals LR & Linked Gel w/24,000# 20/40 sand.
- 9-23-82 - Ran 139 jts (4,309') 2-3/8" OD tbg @ 4,324' w/SN @ 4,293'. Remove BOP, install tbg bonnet & ran pump and rods.

18. I hereby certify that the foregoing is true and correct

SIGNED J.R. Hughes TITLE Dist Drlg. Supt. DATE 9-29-82

(This space for Federal or State office use)

ACCEPTED FOR RECORD  
CONDITIONS OF APPROVAL, IF ANY:  
S.S.J.  
SEP 20 1983

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

\*See Instructions on Reverse Side