Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

JUL 1 9 2004

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

OPP-ARTESIA

5. Lease Serial No.
NM-76936
6. If Indian, Allottee or Tribe Name

				•	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agre	eement, Name and/or No.
Type of Well					
Oil Well X Gas Well Other				8. Well Name and No.	
2. Name of Operator				Sunflower AHW Federal #2	
Yates Petroleum Corporation				9. API Well No.	
3a. Address 3b. Phone No. (include area code)				30-015-27525	
105 S. 4th Str., Artesia, NM 88210 505-748-1471				10. Field and Pool,	or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)				Siegrest Draw	•
			11. County or Parish, State		
660'FNL & 660'FEL of Section 31-T19S-R24E (Unit A, NENE)				Eddy County, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE				PORT, OR OT	HER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
X Notice of Intent	Acidize Deepen Proc		Production (S	tion (Start/Resume) Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity
	Casing Repair	New Construction	Recomplete		Other
Subsequent Report	Change Plans	X Plug and Abandon	Temporarily .	y Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	Water Disposal	
13. Describe Proposed of Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)					
Yates Petroleum Corporation plans to plug and abandon this well as follows:					
1. Rig up all safety equipment needed.					
2. TIH with tubing open ended to +/-4150', circulate hole with 9.5# mud.					
3. PUH to +/-3890' and pump 25 sx Class "C" cement for 100' plug inside 5-1/2" casing.					
4. PUH to +/-1485' laying down +/-2405' 2-7/8" tubing and pump 25 sx cement with additives for 100' plug in 5-1/2" casing					
Tag plug.					
5. Perforate casing at 426' and test casing to 500 psi. If holds, spot 100' plug inside 5-1/2" casing. If test does not hold,					
spot 100' plug adding 2% CaCl2 to cement. Tag plug.					
6. Perforate casing at 60' and test casing to 500 psi. If holds, spot 60' plug inside 5-1/2" casing. If test does not hold,					
circulate 60' plug to surface. Tag plug.					
7. Cut off wellhead and install marker.					
NOTE: Yates Petroleum Corporation will use steel pits and no earth pits					
14. I hereby certify that the foregoing is true ar	nd correct	.ocp			
Name <i>(Printed/Typed)</i> Tina Huerta		NMO THE Regul	atony Complia	nce Superviso	· vr
1 ma riuerta	+ tok record	inte ixegui	atory Compila	rice Superviso	<u> </u>
Signature Jina, Hue	nd correct	Date July 1	5, 2004		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by		Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office					
which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United					



