Submit 3 Copies To Appropriate District	State of New Mo	State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-63447		
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505		LG-2622			
SUNDRY NOTICES AND REPORTS ON WELLS				Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			or contrigionment runte.		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Harvest ABR State		
1. Type of Well:		13.7°			
Oil Well Gas Well X	Other /v	To Tale			
2. Name of Operator	1 98	5 7 5	8. Well No.		
Yates Petroleum Corpor 3. Address of Operator	(1)		4	77711	
-	ia, NM 88210		9. Pool name or		
7,1103	13, 11W 00210	F 150/	Foor Ranch W	olicamp	
4. Well Location	- Fe9>c	24262726			
Unit Letter K: 1980 feet from the South line and 1650 feet from the West line					
Section 36	T1: 00 P	0.45			
Section 38	Township 9S Range 10. Elevation (Show whether D.		MPM Chay	/es County	
	3547		9		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON			ALTERING	
TEN GRINTEINEBIAE WORK	PLOG AND ABANDON	REMEDIAL WOR	` <u> </u>	CASING	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRII			PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB	ID .		
OTHER:					
		OTHER: Perforate		X	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
4/4-6/03 - Perforate Wolfcamp 4509'-4519' (60). Set packer at 4400'.					
4/7/03 – Acidize with 100g 7-1/2% IC acid and 90 balls.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE					
Type or print name Ting Huerto	1		Telenhone No	505-748-1471	
(This space for State Ase)				JUJ-7 40-147 I	
//)(Q/ A ·					
APPPROVED BY Conditions of approval, if any:	TITLE_	WANKE &	7-00	_DATE APR 1 6 2003	