Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-29

District Office	-	•	
DISTRICT I P.O. Box 1940, Hobbs, NM \$4240 P.O. Box 2088			WELL API NO 30-015-01485
DISTRICT II P.O. Drawer DD, Artonia, NM \$\$210	Santa Fe, New Mexico		S. Indicate Type of Losse
DISTRICT III 1000 Rio Brizos Rd., Azioc, NM 17410			STATE X FEE
<u></u>			B-8435
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	CES AND REPORTS ON WE PPOSALS TO DRILL OR TO DEEPER RVOIR, USE "APPLICATION FOR PE 101) FOR SUCH PROPOSALS,)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: Out GAS WELL XX WELL .	OTHER	RECEIVED	Red Lake Sand Unit
2. Name of Operator Mack Energy Corpo	ration	APR 1 9 2004	8. Well Na 21
3. Address of Operator		- OCD-ARTESI	9. Pool name or Wildcat
P.O. Box 960, Art	esia, NM 88211-0960		Red Lake; Queen-Grayburg-SA
4. Well Location P 66	0 Court	660	Feet From The East Line
Unit Letter P: 66	O Feet From The South	Line and	Feet From The Line
Section 20	Township 17S R	28E	NMPM Eddy County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
11. Check A	Appropriate Box to Indicate	Nature of Notice, R	eport, or Other Data
NOTICE OF INT	•••		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT X
PULL OR ALTER CASING	_	CASING TEST AND CE	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operationally SEE RULE 1103.	cos (Clearly state all persinent details, a	nd give pertinent dates, includ	ting estimated date of starting any proposed
3-31-04 Spot 35 sx cm 3-31-04 Spot 35 sx cm 4-01-04 Tag @ 1601'. 4-01-04 Circ. hole w/	nt. @ 1782'.		
4-01-04 Perf. 4 holes		. down 8-5/8" t	o surface around outside
4-02-04 Tag plug @ 3'	· CO Syo Tull Of CML.	•	
	dry hole marker & cle	ean location.	
I benety certify that the information above is true	and complete to the back of my knowledge and	batial.	
SIGNATURE & M	//m	Agent_	DATE 4-13-04
THEOREMINAME Roger Mass	ey	·	ТВЕ Е ТНОМЕ НО. 432-530-090
(This space for State Use)		À -	11 1 70



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

P/A Ot to Relace
10/20/04

Lori Wrotenbery
Director
Oil Conservation Division

RECEIVED

OCT 1 5 2004

4 May 2004

Mack Energy Corporation P.O. Box 960 Artesia, New Mexico 88211-0960

Form C-103 Report of Plugging for your RedLake Sand Unit 21 P-20-17-28 API 30-015-01485 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been filled and leveled.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 2 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Van Barton

Jame W. Shenell Production Check