

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 16 2012

Form C-141
Revised October 10, 2003

NMOCD ARTESIA
Appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nMLB/211638784 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: Turner B North #8	Facility Type: Injection	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001505280

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	20	17S	31E	660	North	1980	East	Eddy

Latitude: 32.825484253602 Longitude: -103.889812477226

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 145 / 5	Volume Recovered: 0 / 2
Source of Release: Pipeline-FG	Date and Hour of Occurrence: 3/28/2012 10:00am	Date and Hour of Discovery: 3/28/2012 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD / Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 3/28/2012 4pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Injection line came apart at the collar. There was evidence of erosion around the threads. Shut in at header. Ru pump trks and pumped 800 bbl fresh water w/ soap to get leak to surface.

Describe Area Affected and Cleanup Action Taken.* : Leak surfaced between the TB#6-inj. and TB #8-inj leak traveled SE towards the TB #102-prod. Further remedial action pending...

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By: <i>Mike Bratcher</i>	
Title: Production Foreman	Approved by District Supervisor:	
E-mail Address: jhernandez@linenergy.com	APR 25 2012	Expiration Date:
Date: 04/16/2012 Phone: 575-942-9492	Approval Date:	Attached <input type="checkbox"/>
Conditions of Approval:		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
5/25/2012

2RP/1110