Form 3160-5 (April 2004)

UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR

FORM APPROVED

BUREAU OF LAND MANAGEMENT

5. Lease Serial No.

NIM	NM	10	36	- C

SUNDRY NOTICES AND REPORTS ON WELLS					NMNM 103603		
Do not use the abandoned we	nis form for proposals t ell. Use Form 3160 - 3 (/	o drill or to re-ea APD) for such pro	nter an posals.	6. If Indiar	a, Allottee or Tribe Name		
SUBMIT IN TR	IPLICATE- Other instr	ructions on revers	se side.	7. If Unit of	r CA/Agreement, Name and/or No.		
1. Type of Well Oil Well □ □	Gas Well□□ □ Other			8. Well Na			
2. Name of Operator OXY USA In	ıc.	10	6696	9. API We	shtalo Federa(#1		
3a. Address P.O. Box 50250 Midland, TX	K 79710	3b. Phone No. (include 432-685-5717	area code)		-40007 d Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R, M., or Survey Description) 5 - 1803 F5L 31 FEC WESE(I) Sec 26 T235 R29E 11. County or Parish, State B. 400 FWL WONDW(D) Eddy NM							
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATURI	E OF NOTICE, R	EPORT, OR	OTHER DATA		
TYPE OF SUBMISSION	,	TYP	E OF ACTION				
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Standard Reclamation Recomplete	art/Resume)	Water Shut-Off Well Integrity Other Spad, Set		
	Change Plans	Plug and Abandon	Temporarily Al	oandon	CER & cont.		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

__ Temporarily Abandon

Water Disposal
 Wate

Spud 17-1/2" hole 4/13/12, drill to 340'. RIH & set 13-3/8" 48# H-40 STC csg @ 340', cmt w/ 240sx (75bbl) PPC w/ additives, followed by 200sx (48bbl) PPC w/ additives, circ 160sx (50bbl) cmt to surf. WOC. Test BOP's @ 250# low 5000# high. WOC per BLM requirements. 4/16/12, RIH & tag cmt @ 283', circ hole, pressure test csg to 1250# for 30min, good test.

FDDM 05/24/12 Capted for record

Convert to Injection

NMOCD ARTESIA

	Control of the Contro					
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)						
David Stewart	Title Regulatory Advisor					
Signature Ju · Stat	Date 411712 ACCEPTED FOR RECORD					
THIS SPÂCE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Title DateAPR 2 3 2012					
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject le which would entitle the applicant to conduct operations thereon.	case Office					
Trtle 18 U.S.C. Section 1001 and Trtle 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fiaudulent statements or representations as to anymatte	person knowingly and willfully to make to an department of appending United a within its jurisdiction.					

Final Abandonment Notice