Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM-0219603
6 If Indian Allottee or Tribe Name

abandoned with out to the close of the sylver state of the sylver				o. II maint, 7 mondo o. This Maine		
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.		
Type of Well			ECENT	7		
Oil Well X Gas Well Other SED					d No.	
Name of Operator Yates Petroleum Corporation					Federal BZ Com #12	
Yates Petroleum Corporation	1		"Edia	9. API Well No.		
Address 3b. Phone No. (include area code)		ode)	30-015-21625			
105 S. 4th Str., Artesia, NM 88210		505-748-1471		10. Field and Pool, or Exploratory Area		
Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)				Eagle Creek	Strawn Permo Penn	
				11. County or Pa	rish, State	
1980'FSL & 1980'FWL of Section 21-T17S-R25E (Unit K, NESW)			Eddy Count	y, New Mexico		
		INDICATE NATURE O	F NOTICE, R		· · · · · · · · · · · · · · · · · ·	
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	Deepen	Production	ı (Start/Resume)	Water Shut-Off	
X Notice of Intent	Alter Casing	Fracture Treat	Reclamatio	on	Well Integrity	
	Casing Repair	New Construction	Recomplet	re	Other	
				Abandon Temporarily Abandon		
Subsequent Report	Change Plans	X Plug and Abandon	Temporari	ly Abandon		

Yates Petroleum Corporation plans to plug and abandon this well as follow:

NOTE: CIBP at 6342' with 35' cement on top

1. Rig up all safety equipement as needed.

determined that the site is ready for final inspection.)

- 2. Circulate hole with 9.5# mud.
- 3. Shoot squeeze holes at 4098'. Spot 100' (35 sx) cement plug from 4098'-3998' in and out of casing.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

- 4. Shoot squeeze holes at 2012'. Spot 100' (35 sx) cement plug from 2012'-1912' in and out of casing.
- 5. Shoot squeeze holes at 1152'. Spot 100' (45 sx) cement plug from 1152'-1052' in and out of casing. Tag plug.
- 6. Shoot squeeze holes at 257'. Circulate casing with cement from 257' (115 sx) to surface in and out of casing. Tag plug.
- 7. Cut off wellhead and install dry hole marker, clean and restore location as per regulated.

NOTE: Yates Petroleum Corporation will use steel pits and no earth pits

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Tina Huerta Title	Regulatory Co	mpliance Supervisor				
Signature lina luerta sate	September 2,	2005				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Title	Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any pers States any false, fictitious or fraudulent statements or representations as to any matter with		o make to any department or agency of the United				



