Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**OCD Artesia** 

FORM APPROVED

	Expires		
ease Ser	al No.		

Expires: July 31, 2010	
5. Lease Serial No. NMNM100558	
6. If Indian, Allottee or Tribe Name	

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM100558  6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
I. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Ot			·	8. Well Name and No. RDX FEDERAL 10 3			
Name of Operator     RKI EXPLORATION & PROD	CHARLES K AHN kixp.com			9. API Well No. 30-015-40870			
3a. Address 210 PARK AVENUE, SUITE OKLAHOMA CITY, OK 7310	3b. Phone No. (include area code) Ph: 405-996-5771 Fx: 405-996-5772			10. Field and Pool, or Exploratory BRUSHY DRAW-DELAWARE EAST			
4. Location of Well (Footage, Sec.,				Ī	11. County or Parish.		
Sec 10 T26S R30E Mer NMF	9 SWSE 1090FSL 2310	FEL	•		EDDY COUNT	Y COUNTY, N	<b>VI</b>
12. CHECK APP	ROPRIATE BOX(ES)	TO INDICATE	NATURE OF NO	OTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION			TYPE OF A	ACTION			
N. d CI	Acidize	□ Dee	pen	Production	on (Start/Resume)	☐ Water Shu	ıt-Off
□ Notice of Intent	Alter Casing	— .	ture Treat	Reclamat	tion	☐ Well Integ	rity
Subsequent Report	Casing Repair	□ New	Construction	Recompl	ete	Other	
Final Abandonment Notice	Change Plans	Plug	and Abandon	Tempora	rily Abandon	Drilling Ope	rations
<u> </u>	Convert to Injection	on Plug	Back	□ Water Di	isposal		÷
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for Spudded the well on 12/21/12 13-3/8 inch 54.5# J-55 STC of	nally or recomplete horizonta ork will be performed or provided operations. If the operation bandonment Notices shall be final inspection.)  2. Drilled 17-1/2 inch ho	lly, give subsurface ide the Bond No. o results in a multip filed only after all le to 985 feet or	locations and measurn file with BLM/BIA. le completion or recor requirements, including 12/23/12. Ran 2	ed and true ve Required sub impletion in a n ing reclamation	rtical depths of all per sequent reports shall be new interval, a Form 3 n, have been completed	tinent markers and be filed within 30 d 160-4 shall be filed d, and the operator	zones. lays l once has
Cementing			•			MMOCD	·. *
Lead: 600 sks of Class C (C	+4%PF20+2%PF1+1.25	#PPSPF29+.25	SPPSPF46). Yield	l = 1.74, Dei	nsity = 13.5	ı	
Tail: 200 sks of Class C (CN	EAT). yield = 0.00. De	nsity = 14.8		•			
Ran temperature survey. cen	nent @ 240 feet				RECE	IVED	
Topout: 255 sks of Class C (	CNEAT topout). Yield =	1.32, Density :	= 14.8		JAN 1	•	
14. Thereby certify that the foregoing	s true and correct. Electronic Submissior	#176710 verifie	d by the BLM Well	Information	NIVIOCD /	HHESIM	
	For RKI EXPLO	RATION & PRO	DUCTION, sent to	the Carlsbac	d		
Name (Printed/Typed) CHARLE	,	Title EH&S/RE	EGULATOR	RY MANAGER		·	
Signature (Electronic	Submission)		Date 01/04/20	13 AC	CEPTED FOI	R RECORD	
,	THIS SPACE	FOR FEDERA	L OR STATE C	FFICE US	SE	0000	
Approved By			Title		muhu	Men	
Conditions of approval, if any, are attached. Approval of this notice does no certify that the applicant holds legal or equitable title to those rights in the su which would entitle the applicant to conduct operations thereon.			Office	, [ [	CARLSBAD FIEL	IANAGEMENT D OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



## Additional data for EC transaction #176710 that would not fit on the form

## 32. Additional remarks, continued

circulated 42 sks on topout stage.

On 12/25/12, tested casing to 1500 psi for 30 minutes = OK.

On 12/27/12, drilled out cement 77.5 hours after cement pumped in place.