OCD Artesia

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010					
	5. Lease Serial No. '. NMNM56429					
	6. If Indian, Allottee of	r Tribe Name				
	7. If Unit or CA/Agree	ment, Name and/or No.				
	8. Well Name and No. TRAVIS D FED 18	3				
	9. API Well No. 30-015-22685-00-S1					
	10. Field and Pool, or Exploratory LOCO HILLS					
	11. County or Parish, and State					
	EDDY COUNTY, NM					
E, RI	EPORT, OR OTHER	R DATA				
)N						
duct	ion (Start/Resume)	■ Water Shut-Off				
clamation		■ Well Integrity				
comp	olete	☐ Other				
mporarily Abandon						
ater Disposal						
any proposed work and approximate duration thereof. rue vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once mation, have been completed, and the operator has						

abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator CARIE STOKER Contact ALAMO PERMIAN RESOURCES LLCE-Mail: cstoker@helmsoil.com 3b. Phone No. (include area code) 415 WEST WALL STREET SUITE 500 Ph: 432-664-7659 MIDLAND, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 17 T18S R29E SENE 1980FNL 660FEL 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE TYPE OF SUBMISSION TYPE OF ACTIO ☑ Pro ☐ Acidize Deepen ■ Notice of Intent □ Alter Casing ☐ Fracture Treat ☐ Re Subsequent Report ☐ Casing Repair ■ New Construction □ Re ☐ Final Abandonment Notice □ Change Plans □ Plug and Abandon ☐ Te ☐ Convert to Injection ☐ Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of a If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and tr Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Require following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclan determined that the site is ready for final inspection.) MIRU. Unhang rods, POOH with rods and pump. ND wellhead. NU BOP. Released TAC and tagged bottom @ 2866'. POOH with 2-3/8" tubing. RIH with 4-1/2" casing scraper to 2850'. PUH above perfs. Set TAC and landed tubing. ND BOP. NU wellhead. RIH with pump and rods. HWO and loaded tubing. Well would not pump. Unseated pump and flushed tubing. Seated pump. Loaded tubing pump, pressured pump to 500 psi. OK. Accepted for record NMOCD 14. I hereby certify that the foregoing is true and correct.

Electronic Submission #179648 verified by the BLM Well Information System

				C,· sent to the Carlsbad IONS on 01/09/2013 (13KMS4350SE)			
Name (Printed/Typed)	CARIE STOKER	1	Title	REGULATORY AFFAIRS COORDINATOR			
Signature	(Electronic Submission)		Date	01/09/2013			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
			T				

Approved By ACCEPTED	JAMES A AMOS _{Title} SUPERVISOR EPS	Date 01/26/2013
Conditions of approval if any are attached. Approval of this notice does not warrant or		

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.